

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N) Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4238 RIDGELAND AVENUE	N/A	N	N	1971	1971		U	U	U	U		9/27/2024	N				100001	
4222 RIDGELAND AVENUE	LC1T017	N	N	1940	1940	Other - Sample Site	U	L	L	L		9/27/2024	N				100008	
4214 RIDGELAND AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				100012	
4206 RIDGELAND AVENUE	N/A	N	N	1942	1942		U	U	U	U		9/27/2024	N				100015	
4132 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100022	
4114 RIDGELAND AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				100027	
4112 RIDGELAND AVENUE	N/A	N	N	1925	1925	Visual Inspection	U	U	L	L		9/27/2024	N				100028	
6407 41ST STREET	N/A	N	N	1953	1953	Visual Inspection	U	U	C	U		9/27/2024	N				100031	
6417 41ST STREET	N/A	N	N	1953	1953	Visual Inspection	U	U	L	L		9/27/2024	N				100036	
4121 ELMWOOD AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				100041	
4125 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100042	
4129 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100043	
4133 ELMWOOD AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100044	
4205 ELMWOOD AVENUE	N/A	N	N	1997	1997	Visual Inspection	C	C	C	NL		N/R	N				100052	
4213 ELMWOOD AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100054	
4217 ELMWOOD AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				100055	
4235 ELMWOOD AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				100061	
4236 ELMWOOD AVENUE	N/A	N	N	1935	1935		U	U	U	U		9/27/2024	N				100067	
4220 ELMWOOD AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				100073	
4216 ELMWOOD AVENUE	N/A	N	N	1970	1970	Visual Inspection	U	U	C	U		9/27/2024	N				100075	
4214 ELMWOOD AVENUE	N/A	N	N	1920	1920		U	U	U	U		9/27/2024	N				100076	
4210 ELMWOOD AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				100077	
4204 ELMWOOD AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				100079	
4202 ELMWOOD AVENUE	N/A	N	N	1914	1914		U	U	U	U		9/27/2024	N				100080	
4134 ELMWOOD AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				100086	
4132 ELMWOOD AVENUE	N/A	N	N	1977	1977		U	U	U	U		9/27/2024	N				100087	
4112 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100093	
4133 GUNDERSON AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				100108	
4205 GUNDERSON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				100114	
4225 GUNDERSON AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100118	
4231 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100120	
4241 GUNDERSON AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				100123	
4238 GUNDERSON AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				100128	
4236 GUNDERSON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100129	
4234 GUNDERSON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				100130	
4230 GUNDERSON AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N				100131	
4226 GUNDERSON AVENUE	N/A	N	N	1930	1930	Visual Inspection	U	U	L	L		9/27/2024	N				100133	
4204 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100139	
4140 GUNDERSON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100145	
4118 1/2 GUNDERSON AVE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				100151	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
6519 41ST STREET	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				100159	
4131 SCOVILLE AVENUE	N/A	N	N	1997	1997	Visual Inspection	C	C	C	NL		N/R	N				100166	
4133 SCOVILLE AVENUE	N/A	N	N	1996	1996	Visual Inspection	C	C	C	NL		N/R	N				100167	
4215 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100177	
4217 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100178	
4223 SCOVILLE AVENUE	N/A	N	N	1963	1963		U	U	U	U		9/27/2024	N				100180	
4227 SCOVILLE AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				100182	
4229 SCOVILLE AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				100183	
4218 SCOVILLE AVENUE	N/A	N	N	1974	1974		U	U	U	U		9/27/2024	N				100198	
4214 SCOVILLE AVENUE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				100200	
4200 SCOVILLE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				100203	
4114 EAST AVENUE	N/A	N	N	1992	1992	Visual Inspection	C	C	C	NL		N/R	N				100208	
4201 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				100209	
4203 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				100210	
4205 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				100211	
4209 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				100213	
4211 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				100214	
4215 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				100216	
4221 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				100219	
4227 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				100222	
4229 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				100223	
4231 EAST AVENUE	N/A	N	N	1957	1957	Visual Inspection	C	C	C	NL		N/R	N				100224	
4237 EAST AVENUE	N/A	N	N	1930	1930	Visual Inspection	C	C	C	NL		N/R	N				100227	
3916 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100230	
3926 SCOVILLE AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				100232	
4000 SCOVILLE AVENUE	LC1T039	N	N	1974	1974	Other - Sample Site	U	L	L	L		9/27/2024	N				100238	
4010 SCOVILLE AVENUE	N/A	N	N	1967	1967		U	U	U	U		9/27/2024	N				100240	
4022 SCOVILLE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				100245	
4024 SCOVILLE AVENUE	N/A	N	N	1950	1950	Visual Inspection	U	U	C	U		9/27/2024	N				100246	
4034 SCOVILLE AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	L	L		9/27/2024	N				100248	
6522 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100249	
6528 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100252	
6532 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100253	
6540 41ST STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				100255	
4025 EAST AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				100258	
3943 EAST AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				100267	
3925 EAST AVENUE	N/A	N	N	1940	1940		U	U	U	U		9/27/2024	N				100272	
3919 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	U	U	C	U		12/15/2025	N				100274	
3913 EAST AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N				100277	
3912 GUNDERSON AVENUE	N/A	N	N	1931	1931	Visual Inspection	U	U	L	L		9/27/2024	N				100278	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
3920 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100280	
3930 GUNDERSON AVENUE	N/A	N	N	1945	1945	Visual Inspection	U	U	U	L		9/27/2024	N				100283	
3942 GUNDERSON AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				100286	
4000 GUNDERSON AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				100288	
4004 GUNDERSON AVENUE	N/A	N	N	2023	2023	Installation Record	C	C	C	NL		N/R	N				100289	
4024 GUNDERSON AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100296	
6508 41ST STREET	LC11010	N	N	1989	1989	Other - Sample Site	U	L	L	L		9/27/2024	N				100302	
6514 41ST STREET	N/A	N	N	1916	1916		U	U	U	U		9/27/2024	N				100304	
6516 41ST STREET	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				100305	
4035 SCOVILLE AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				100308	
4029 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100310	
4003 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100320	
3933 SCOVILLE AVENUE	N/A	N	N	1955	1955	Visual Inspection	U	U	L	L		9/27/2024	N				100325	
3919 SCOVILLE AVENUE	N/A	N	N	1952	1952	Visual Inspection	U	U	L	L		9/27/2024	N				100329	
3915 SCOVILLE AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				100331	
3911 SCOVILLE AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				100332	
3912 ELMWOOD AVENUE	LC11038	N	N	1962	1962	Other - Sample Site	U	L	L	L		9/27/2024	N				100333	
3916 ELMWOOD AVENUE	N/A	N	N	1952	1952	Visual Inspection	U	U	C	U		12/15/2025	N				100335	
3928 ELMWOOD AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				100338	
3932 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100339	
4024 ELMWOOD AVENUE	N/A	N	N	1997	1997	Visual Inspection	C	C	C	NL		N/R	N				100349	
6430 41ST STREET	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100354	
4029 GUNDERSON AVENUE	N/A	N	N	1937	1937		U	U	U	U		9/27/2024	N				100359	
4009 GUNDERSON AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				100365	
3943 GUNDERSON AVENUE	N/A	N	N	1976	1976		U	U	U	U		9/27/2024	N				100369	
3919 GUNDERSON AVENUE	N/A	N	N	1948	1948		U	U	U	U		9/27/2024	N				100377	
3913 GUNDERSON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				100379	
3912 RIDGELAND AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100381	
3920 S RIDGELAND AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				100383	
3914 RIDGELAND AVENUE	N/A	N	N	1915	1915		U	U	U	U		9/27/2024	N				100384	
3936 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100387	
4008 RIDGELAND AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				100393	
4012 RIDGELAND AVENUE	LC11035	N	N	1925	1925	Other - Sample Site	U	L	L	L		9/27/2024	N				100394	
6400 41ST STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100402	
6420 41ST STREET	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				100407	
4029 ELMWOOD AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				100409	
4025 ELMWOOD AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				100410	
4021 ELMWOOD AVENUE	N/A	N	N	1920	1920		U	U	U	U		9/27/2024	N				100411	
4011 ELMWOOD AVENUE	N/A	N	N	1940	1940		U	U	U	U		9/27/2024	N				100414	
4001 ELMWOOD AVENUE	LC11003	N	N	1955	1955	Other - Sample Site	U	L	L	L		9/27/2024	N				100417	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned Service Line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
3931 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100422	
3911 ELMWOOD AVENUE	N/A	N	N	1962	1962	Visual Inspection	U	U	C	U		12/15/2025	N				100428	
3944 EUCLID AVENUE	N/A	N	N	1969	1969		U	U	U	U		9/27/2024	N				100438	
4034 EUCLID AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				100442	
4036 EUCLID AVENUE	N/A	N	N	1922	1922		U	U	U	U		9/27/2024	N				100443	
6734 41ST STREET	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				100448	
6742 41ST STREET	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				100450	
4027 OAK PARK AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100451	
4017 OAK PARK AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100455	
4013 OAK PARK AVENUE	LC1T029	N	N	1959	1959	Other - Sample Site	U	L	L	L		9/27/2024	N				100456	
4011 OAK PARK AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				100457	
3945 OAK PARK AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				100460	
3943 OAK PARK AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				100461	
3921 OAK PARK AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				100468	
3924 WESLEY AVENUE	N/A	N	N	1931	1931	Visual Inspection	U	U	L	L		9/27/2024	N				100477	
3930 WESLEY AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100478	
3940 WESLEY AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				100480	
3942 WESLEY AVENUE	N/A	N	N	1916	1916		U	U	U	U		9/27/2024	N				100481	
3944 WESLEY AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				100482	
4010 WESLEY AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100485	
4016 WESLEY AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	L	L		9/27/2024	N				100487	
4020 WESLEY AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				100488	
4022 WESLEY AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				100489	
4032 WESLEY AVENUE	N/A	N	N	1989	1989	Visual Inspection	U	U	C	U		12/15/2025	N				100493	
6714 41ST STREET	N/A	N	N	1970	1970		U	U	U	U		9/27/2024	N				100498	
4033 EUCLID AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				100501	
4005 EUCLID AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				100509	
4001 EUCLID AVENUE	N/A	N	N	2023	2023		U	U	U	U		9/27/2024	N				100510	
3945 EUCLID AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				100511	
3929 EUCLID AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				100516	
3944 CLARENCE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100529	
4000 CLARENCE AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				100530	
4022 CLARENCE AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				100537	
4028 CLARENCE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				100539	
6630 41ST STREET	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				100543	
6638 W 41ST STREET	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100545	
4027 WESLEY AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				100550	
4025 WESLEY AVENUE	N/A	N	N	1952	1952	Visual Inspection	U	U	L	L		9/27/2024	N				100551	
4019 WESLEY AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				100552	
4017 WESLEY AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				100553	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name		Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026					
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4011 WESLEY AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				100555	
4005 WESLEY AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100557	
3941 WESLEY AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				100561	
3912 EAST AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100569	
3918 EAST AVENUE	LC1T026	N	N	1962	1962	Other - Sample Site	U	L	L	L		9/27/2024	N				100571	
3928 EAST AVENUE	N/A	N	N	1917	1917		U	U	U	U		9/27/2024	N				100574	
3940 EAST AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				100577	
3942 EAST AVENUE	N/A	N	N	1939	1939		U	U	U	U		9/27/2024	N				100578	
4006 EAST AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				100581	
4010 EAST AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100582	
6616 41ST STREET	LC1T012	N	N	1987	1987	Other - Sample Site	U	L	L	L		9/27/2024	N				100595	
6618 41ST STREET	N/A	N	N	1988	1988		U	U	U	U		9/27/2024	N				100596	
4027 CLARENCE AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				100599	
4025 CLARENCE AVENUE	N/A	N	N	1955	1955	Visual Inspection	U	U	C	U		12/15/2025	N				100600	
4021 CLARENCE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100601	
4011 CLARENCE AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				100604	
4005 CLARENCE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100606	
3939 CLARENCE AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				100609	
3915 CLARENCE AVENUE	N/A	N	N	1915	1915	Visual Inspection	U	U	L	L		9/27/2024	N				100616	
6613 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				100619	
6625 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				100624	
6631 41ST STREET	N/A	N	N	1978	1978	Visual Inspection	U	U	C	U		9/27/2024	N				100626	
6639 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				100629	
6645 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				100631	
6705 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				100632	
6707 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				100633	
6709 W 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				100634	
6711 41ST STREET	N/A	N	N	1979	1979		U	U	U	U		9/27/2024	N				100635	
4132 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100642	
4130 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100643	
4126 MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				100645	
4116 MAPLE AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				100648	
4110 MAPLE AVENUE	N/A	N	N	1923	1923		U	U	U	U		9/27/2024	N				100650	
4108 MAPLE AVENUE	N/A	N	N	1922	1922		U	U	U	U		9/27/2024	N				100651	
4103 MAPLE AVENUE	N/A	N	N	1995	1995	Visual Inspection	C	C	C	NL		N/R	N				100656	
4113 MAPLE AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				100660	
4123 MAPLE AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				100664	
4125 MAPLE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100665	
4101 WISCONSIN AVENUE	N/A	N	N	1982	1982		U	U	U	U		9/27/2024	N				100669	
4105 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				100692	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4125 WISCONSIN AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100699	
4135 WISCONSIN AVENUE	N/A	N	N	1964	1964	Visual Inspection	U	U	U	U		9/27/2024	N				100702	
4137 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				100703	
4122 WENONAH AVENUE	N/A	N	N	1949	1949	Visual Inspection	U	U	L	L		9/27/2024	N				100712	
4116 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100714	
4114 WENONAH AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				100715	
4108 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100717	
4101 WENONAH AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				100720	
4103 WENONAH AVENUE	N/A	N	N	1996	1996		U	U	U	U		9/27/2024	N				100721	
4107 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100723	
4121 WENONAH AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				100728	
4127 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100731	
4137 WENONAH AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				100735	
4132 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100742	
4128 HOME AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				100743	
4120 HOME AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N				100746	
4118 HOME AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				100747	
4108 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				100751	
4103 HOME AVENUE	N/A	N	N	1962	1962	Visual Inspection	U	U	C	U		9/27/2024	N				100756	
4105 HOME AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				100757	
4115 HOME AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				100762	
4137 HOME AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100764	
4143 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				100766	
4136 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				100770	
4134 CLINTON AVENUE	N/A	N	N	1952	1952	Visual Inspection	U	U	U	U		9/27/2024	N				100771	
4126 CLINTON AVENUE	N/A	N	N	1952	1952	Other - Sample Site	U	L	L	L		12/15/2025	N				100774	
4118 CLINTON AVENUE	LC1T006	N	N	1952	1952		U	L	L	L		9/27/2024	N				100777	
4116 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				100778	
4108 CLINTON AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				100781	
4100 CLINTON AVENUE	LC1T005	N	N	1952	1952	Other - Sample Site	U	L	L	L		9/27/2024	N				100783	
4101 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				100784	
4103 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				100785	
4105 CLINTON AVENUE	N/A	N	N	1950	1950	Visual Inspection	U	U	L	L		9/27/2024	N				100786	
4121 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				100790	
4125 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				100791	
4132 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100804	
4104 GROVE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				100813	
4103 GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100817	
4123 GROVE AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				100823	
4125 GROVE AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				100824	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4131 GROVE AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	L	L		9/27/2024	N				100826	
4135 GROVE AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				100827	
4145 GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100830	
4148 OAK PARK AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				100831	
4144 OAK PARK AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	C	U		12/15/2025	N				100832	
4136 OAK PARK AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				100835	
4126 OAK PARK AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				100839	
4020 OAK PARK AVENUE	N/A	N	N	1998	1998		U	U	U	U		9/27/2024	N				100854	
4016 OAK PARK AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				100856	
4006 OAK PARK AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				100860	
4035 GROVE AVENUE	N/A	N	N	1950	1950	Visual Inspection	U	U	C	U		9/27/2024	N				100861	
4024 GROVE AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				100871	
4020 GROVE AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				100872	
4014 GROVE AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				100875	
4006 GROVE AVENUE	LCT1020	N	N	1919	1919	Other - Sample Site	U	L	L	L		9/27/2024	N				100878	
4004 GROVE AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				100879	
4000 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100880	
4015 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				100887	
4045 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100898	
4042 CLINTON AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				100900	
4026 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100905	
4014 CLINTON AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				100911	
4008 CLINTON AVENUE	N/A	N	N	1976	1976		U	U	U	U		9/27/2024	N				100913	
4011 HOME AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				100919	
4021 HOME AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				100923	
4027 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100925	
4041 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100930	
7012 41ST STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				100933	
7038 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				100942	
7042 41ST STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				100943	
7052 41ST STREET	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				100945	
7102 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100946	
7104 41ST STREET	N/A	N	N	1970	1970		U	U	U	U		9/27/2024	N				100947	
7106 41ST STREET	N/A	N	N	1970	1970		U	U	U	U		9/27/2024	N				100948	
7128 41ST STREET	LCT1014	N	N	1986	1986	Other - Sample Site	U	L	L	L		9/27/2024	N				100955	
7113 40TH PLACE	N/A	N	N	1917	1917		U	U	U	U		9/27/2024	N				100969	
7111 40TH PLACE	N/A	N	N	1979	1979		U	U	U	U		9/27/2024	N				100970	
7101 40TH PLACE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				100973	
7041 40TH PLACE	N/A	N	N	1916	1916		U	U	U	U		9/27/2024	N				100976	
7037 40TH PLACE	N/A	N	N	1976	1976	Visual Inspection	U	U	C	U		12/15/2025	N				100978	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
7035 40TH PLACE	N/A	N	N	1977	1977		U	U	U	U		9/27/2024	N				100979	
7007 40TH PLACE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				100988	
7001 40TH PLACE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				100991	
7000 40TH PLACE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				100992	
7004 40TH PLACE	N/A	N	N	1975	1975		U	U	U	U		9/27/2024	N				100994	
7020 40TH PLACE	N/A	N	N	1971	1971	Visual Inspection	U	U	C	U		9/27/2024	N				100999	
7024 40TH PLACE	N/A	N	N	1971	1971		U	U	U	U		9/27/2024	N				101001	
7030 40TH PLACE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				101004	
7042 40TH PLACE	N/A	N	N	1914	1914		U	U	U	U		9/27/2024	N				101007	
7046 40TH PLACE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				101009	
7114 40TH PLACE	N/A	N	N	1914	1914		U	U	U	U		9/27/2024	N				101014	
7116 40TH PLACE	N/A	N	N	1998	1998		U	U	U	U		9/27/2024	N				101015	
7122 40TH PLACE	N/A	N	N	1965	1965		U	U	U	U		9/27/2024	N				101017	
7124 40TH PLACE	N/A	N	N	1919	1919	Visual Inspection	U	U	L	L		9/27/2024	N				101018	
7126 40TH PLACE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101019	
7132 40TH PLACE	N/A	N	N	1990	1990	Visual Inspection	C	C	C	NL		N/R	N				101021	
7133 40TH STREET	N/A	N	N	1956	1956	Visual Inspection	U	U	L	L		9/27/2024	N				101023	
7131 40TH STREET	N/A	N	N	1914	1914		U	U	U	U		9/27/2024	N				101024	
7119 40TH STREET	N/A	N	N	1914	1914	Visual Inspection	U	U	C	U		9/27/2024	N				101028	
7117 40TH STREET	N/A	N	N	1993	1993	Visual Inspection	C	C	C	NL		N/R	N				101029	
7115 40TH STREET	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				101030	
7105 40TH STREET	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				101033	
7043 40TH STREET	N/A	N	N	1981	1981		U	U	U	U		9/27/2024	N				101036	
7039 40TH STREET	N/A	N	N	1979	1979		U	U	U	U		9/27/2024	N				101038	
7009 40TH STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				101050	
3928 OAK PARK AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				101060	
3920 OAK PARK AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				101062	
3918 OAK PARK AVENUE	N/A	N	N	1951	1951	Visual Inspection	U	U	C	U		9/27/2024	N				101063	
3921 GROVE AVENUE	LC1T002	N	N	1988	1988	Other - Sample Site	U	L	L	L		9/27/2024	N				101071	
3931 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101076	
3942 GROVE AVENUE	N/A	N	Y	1930	1930	Visual Inspection	U	L	L	L		9/27/2024	N				101079	
3914 GROVE AVENUE	N/A	N	N	1974	1974		U	U	U	U		9/27/2024	N				101089	
3929 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				101097	
3935 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				101100	
3939 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				101102	
3941 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				101103	
3926 CLINTON AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				101109	
3914 CLINTON AVENUE	N/A	N	N	1957	1957	Visual Inspection	U	U	C	U		9/27/2024	N				101115	
6935 PERSHING ROAD	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				101117	
6937 PERSHING ROAD	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				101118	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LX". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
6939 PERSHING ROAD	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				101119	
6941 PERSHING ROAD	N/A	N	N	1957	1957	Visual Inspection	U	U	C	U		9/27/2024	N				101120	
3915 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				101125	
3917 HOME AVENUE	N/A	N	N	1950	1950	Visual Inspection	U	U	C	U		9/27/2024	N				101126	
3925 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				101130	
3900 HOME AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				101137	
3944 HOME AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				101148	
7004 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				101149	
7020 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				101153	
7032 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				101156	
7040 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				101158	
7052 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				101161	
7108 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				101164	
7101 PERSHING ROAD	N/A	N	N	1909	1909	Visual Inspection	U	U	L	L		9/27/2024	N				101170	
7105 PERSHING ROAD	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				101171	
3920 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				101179	
3924 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				101180	
7101 LORRAINE TERRACE	N/A	N	N	1949	1949	Visual Inspection	U	U	L	L		9/27/2024	N				101183	
7033 LORRAINE TERRACE	LC17031	N	N	1948	1948	Visual Inspection	U	L	L	L		9/27/2024	N				101189	
7029 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				101190	
3916 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				101203	
3912 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				101204	
7032 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				101218	
4203 MAPLE AVENUE	N/A	N	N	1968	1968	Visual Inspection	U	U	C	U		12/15/2025	N				101236	
4219 MAPLE AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				101241	
4225 MAPLE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				101243	
7120 43RD STREET	N/A	N	Y	1954	1954	Visual Inspection	U	U	C	U		9/27/2024	N				101247	
4226 WISCONSIN AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				101255	
4201 WISCONSIN AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101264	
4207 1/2 WISCONSIN AVENUE	N/A	N	N	1993	1993	Visual Inspection	C	C	C	NL		N/R	N				101267	
7034 43RD STREET	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				101278	
4218 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				101287	
4200 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				101292	
4209 WENONAH AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				101296	
4213 WENONAH AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				101297	
4237 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				101304	
7024 43RD STREET	N/A	N	N	1970	1970		U	U	U	U		9/27/2024	N				101305	
7006 43RD STREET	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				101311	
7004 43RD STREET	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				101312	
4230 HOME AVENUE	N/A	N	N	1933	1933	Visual Inspection	U	U	C	U		12/15/2025	N				101314	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4228 HOME AVENUE	N/A	N	N	1925	1925	Visual Inspection	U	U	L	L		9/27/2024	N					101315
4224 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					101316
4218 HOME AVENUE	N/A	N	N	1937	1937		U	U	U	U		9/27/2024	N					101318
4216 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N					101319
4203 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					101325
4217 HOME AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N					101329
4221 HOME AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N					101331
4225 HOME AVENUE	N/A	N	N	1963	1963		U	U	U	U		9/27/2024	N					101333
4229 HOME AVENUE	N/A	N	N	1994	1994	Visual Inspection	C	C	C	NL		N/R	N					101335
4239 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					101338
4240 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					101342
4236 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					101343
4228 CLINTON AVENUE	N/A	N	N	1954	1954	Visual Inspection	U	U	L	L		9/27/2024	N					101346
4204 CLINTON AVENUE	N/A	N	N	1899	1899		U	U	U	U		9/27/2024	N					101353
4200 CLINTON AVENUE	N/A	N	N	1973	1973		U	U	U	U		9/27/2024	N					101354
4205 CLINTON AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N					101357
4207 CLINTON AVENUE	N/A	N	N	1954	1954	Visual Inspection	U	U	L	L		9/27/2024	N					101358
4229 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					101367
4237 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N					101369
4238 GROVE AVENUE	N/A	N	N	1979	1979		U	U	U	U		9/27/2024	N					101374
4228 GROVE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N					101376
4226 GROVE AVENUE	N/A	N	N	1955	1955	Visual Inspection	U	U	C	U		12/15/2025	N					101377
4218 GROVE AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N					101380
4216 GROVE AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N					101381
4204 GROVE AVENUE	N/A	N	N	1954	1954	Visual Inspection	U	U	C	U		12/15/2025	N					101384
4219 GROVE AVENUE	N/A	N	N	1976	1976		U	U	U	U		9/27/2024	N					101392
4223 GROVE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N					101393
4231 GROVE AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N					101395
4235 GROVE AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N					101396
4239 GROVE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N					101398
4218 OAK PARK AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N					101404
4210 OAK PARK AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N					101406
4208 OAK PARK AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N					101407
4200 OAK PARK AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N					101410
4306 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N					101414
4330 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N					101426
4331 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N					101427
4327 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N					101429
4323 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N					101431
4311 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N					101437

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned Service Line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4307 MAPLE AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				101439	
4302 WISCONSIN AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				101444	
4314 WISCONSIN AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				101448	
4322 WISCONSIN AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				101450	
4334 WISCONSIN AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				101454	
4338 WISCONSIN AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				101456	
4329 WISCONSIN AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				101461	
7029 43RD STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101470	
4332 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101478	
4336 WENONAH AVENUE	N/A	N	N	1969	1969	Visual Inspection	U	U	L	L		9/27/2024	N				101479	
4337 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				101485	
4329 WENONAH AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				101486	
7021 43RD STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				101490	
7011 43RD STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				101493	
7005 43RD STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101495	
7001 43RD STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101496	
4312 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				101497	
4320 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				101499	
4334 HOME AVENUE	N/A	N	N	1951	1951	Visual Inspection	U	U	L	L		9/27/2024	N				101502	
4340 HOME AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				101504	
4344 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101505	
4337 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101507	
4313 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				101513	
6927 43RD STREET	N/A	N	N	1955	1955	Visual Inspection	U	U	L	L		9/27/2024	N				101516	
4324 CLINTON AVENUE	N/A	N	N	1934	1934		U	U	U	U		9/27/2024	N				101520	
4345 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101526	
4333 CLINTON AVENUE	N/A	N	N	1939	1939		U	U	U	U		9/27/2024	N				101528	
4329 CLINTON AVENUE	N/A	N	N	1938	1938		U	U	U	U		9/27/2024	N				101529	
4315 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				101534	
6905 43RD STREET	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				101538	
4300 KENILWORTH AVENUE	N/A	N	N	1993	1993	Visual Inspection	C	C	C	NL		N/R	N				101540	
4332 KENILWORTH AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				101545	
4341 KENILWORTH AVENUE	N/A	N	N	1988	1988		U	U	U	U		9/27/2024	N				101548	
4346 KENILWORTH AVENUE	N/A	N	N	1952	1952	Visual Inspection	U	U	C	U		9/27/2024	N				101549	
4343 KENILWORTH AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				101550	
4319 KENILWORTH AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				101555	
4317 KENILWORTH AVENUE	N/A	N	N	1966	1966		U	U	U	U		9/27/2024	N				101556	
4315 KENILWORTH AVENUE	N/A	N	N	1967	1967		U	U	U	U		9/27/2024	N				101557	
6829 43RD STREET	N/A	N	N	1959	1959	Visual Inspection	U	U	C	U		12/15/2025	N				101563	
6825 43RD STREET	LC11021	N	N	1955	1955	Other - Sample Site	U	L	L	L		9/27/2024	N				101564	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / / Leave blank if customer has not refused access.	
4320 GROVE AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	C	U		12/15/2025	N				101565	
4342 GROVE AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				101570	
4343 GROVE AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				101576	
4335 GROVE AVENUE	N/A	N	N	1946	1946	Visual Inspection	U	U	L	L		9/27/2024	N				101578	
4321 GROVE AVENUE	N/A	N	N	1948	1948		U	U	U	U		9/27/2024	N				101581	
4310 OAK PARK AVENUE	LC1T034	N	N	1954	1954	Other - Sample Site	U	L	L	L		9/27/2024	N				101583	
4314 OAK PARK AVENUE	N/A	N	N	U	U		U	U	U	U		9/27/2024	N				101584	
4326 OAK PARK AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				101588	
4400 OAK PARK AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				101592	
4404 OAK PARK AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				101593	
4412 OAK PARK AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				101595	
4426 OAK PARK AVENUE	N/A	N	N	1988	1988		U	U	U	U		9/27/2024	N				101598	
4440 OAK PARK AVENUE	N/A	N	Y	1959	1959	Visual Inspection	U	L	L	L		9/27/2024	N				101603	
4454 OAK PARK AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N				101604	
4457 GROVE AVENUE	LC1T040	N	N	1947	1947	Other - Sample Site	U	L	L	L		9/27/2024	N				101606	
4453 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U		9/27/2024	N				101607	
4445 GROVE AVENUE	N/A	N	N	1945	1945	Visual Inspection	U	U	L	L		9/27/2024	N				101609	
4441 GROVE AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				101610	
4437 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U		9/27/2024	N				101611	
4413 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U		9/27/2024	N				101617	
4409 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U		9/27/2024	N				101618	
4404 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101622	
4416 GROVE AVENUE	N/A	N	N	1965	1965		U	U	U	U		9/27/2024	N				101625	
4434 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U		9/27/2024	N				101629	
4459 KENILWORTH AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				101635	
4447 KENILWORTH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				101637	
4427 KENILWORTH AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				101642	
4419 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				101644	
4412 KENILWORTH AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				101652	
4418 KENILWORTH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				101653	
4428 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				101655	
4440 KENILWORTH AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N				101658	
4446 KENILWORTH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				101660	
4431 CLINTON AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				101667	
4410 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				101678	
4414 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				101679	
4420 CLINTON AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				101680	
4428 CLINTON AVENUE	N/A	N	N	1990	1990	Visual Inspection	C	C	C	NL		N/R	N				101682	
4440 CLINTON AVENUE	LC1T009	N	N	1951	1951	Visual Inspection	U	L	L	L		9/27/2024	N				101686	
4433 HOME AVENUE	N/A	N	N	1956	1956	Visual Inspection	U	U	U	U		9/27/2024	N				101693	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LX". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4419 HOME AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				101696	
4411 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101698	
4437 WENONAH AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				101704	
4431 WENONAH AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				101705	
4421 WENONAH AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				101708	
4415 WENONAH AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				101709	
4402 WENONAH AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				101711	
4408 WENONAH AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				101713	
4420 WENONAH AVENUE	LC1T024	N	N	1954	1954	Other - Sample Site	U	L	L	L		9/27/2024	N				101716	
4426 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				101718	
4415 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				101731	
4412 WISCONSIN AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				101735	
4438 WISCONSIN AVENUE	N/A	N	N	1968	1968	Visual Inspection	U	U	C	U		12/15/2025	N				101740	
4442 WISCONSIN AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				101742	
4437 MAPLE AVENUE	N/A	N	N	1940	1940		U	U	U	U		9/27/2024	N				101746	
4431 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101747	
4421 MAPLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				101749	
4415 MAPLE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				101750	
4411 MAPLE AVENUE	N/A	N	N	2006	2006	Visual Inspection	C	C	C	NL		N/R	N				101751	
4401 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				101753	
4422 MAPLE AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				101760	
4438 MAPLE AVENUE	N/A	N	N	1998	1998		U	U	U	U		9/27/2024	N				101763	
4442 MAPLE AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				101764	
41TH AND EUCLID	N/A	N	N				U	U	U	U		9/27/2024	N				101769	
4220 EAST AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101770	
43RD AND EAST AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101771	
4101 OAK PARK AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101772	
6501 PERSHING ROAD	N/A	N	N			Visual Inspection	U	U	C	U		9/27/2024	N				101780	
3904 GUNDERSON AVENUE	N/A	N	N			Visual Inspection	U	U	C	U		9/27/2024	N				101781	
3906 GUNDERSON AVENUE	N/A	N	N			Visual Inspection	U	U	L	L		9/27/2024	N				101782	
6441 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				101784	
6421 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				101785	
6431 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				101786	
6401 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				101788	
6743 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				101789	
6739-41 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				101791	
6721 40TH STREET	N/A	N	N				U	U	U	U		9/27/2024	N				101798	
4143 HARLEM AVENUE	N/A	N	N	1965	1965		U	U	U	U		9/27/2024	N				101820	
4108 OAK PARK AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101823	
6825 40TH STREET	N/A	N	N				U	U	U	U		9/27/2024	N				101824	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4029 HARLEM AVENUE	N/A	N	N	1973	1973		U	U	U	U		9/27/2024	N				101829	
4023 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101830	
4003 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101831	
6905 PERSHING ROAD	N/A	N	N	1995	1995		U	U	U	U		9/27/2024	N				101843	
7122 40TH STREET	N/A	N	N				U	U	U	U		9/27/2024	N				101848	
4201 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101850	
4209 HARLEM AVENUE	N/A	N	N	1996	1996		U	U	U	U		9/27/2024	N				101853	
4211 HARLEM AVENUE	N/A	N	N	1996	1996		U	U	U	U		9/27/2024	N				101854	
4217 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101856	
4227 HARLEM AVENUE	N/A	N	N	1941	1941		U	U	U	U		9/27/2024	N				101859	
4235 HARLEM AVENUE	N/A	N	N			Visual Inspection	U	U	C	U		9/27/2024	N				101861	
6800 43RD STREET	N/A	Y	N				U	U	U	U		9/27/2024	N				101863	
4307 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101872	
6805 43RD STREET	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				101877	
4100 JOLIET AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101878	
3740 CICERO AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101882	
4100 JOLIET AVE	N/A	N	N				U	U	U	U		9/27/2024	N				101884	
4950 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				101893	
3900 LARAMIE AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101894	
3900 LARAMIE AVE	N/A	N	N				U	U	U	U		9/27/2024	N				101895	
3900 LARAMIE AVE	N/A	N	N				U	U	U	U		9/27/2024	N				101896	
4100 LARAMIE AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101897	
4100 CICERO AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101898	
5000 41ST STREET EAST	N/A	N	N				U	U	U	U		9/27/2024	N				101899	
3910 CICERO AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101901	
3800 LARAMIE AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				101904	
37TH & LARAMIE AVE WEST	N/A	N	N				U	U	U	U		9/27/2024	N				101906	
37TH & CICERO AVENUE EAST	N/A	N	N				U	U	U	U		9/27/2024	N				101907	
4232 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				101934	
3924 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101943	
4028 GROVE AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N				101945	
3926 GROVE AVENUE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				101946	
3928 GROVE AVENUE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				101953	
6629 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				101959	
4146 ELMWOOD AVENUE	N/A	N	N	1967	1967		U	U	U	U		9/27/2024	N				101960	
4119 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				101974	
3917 EAST AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				101976	
4001 OAK PARK AVENUE	N/A	N	N	1968	1968		U	U	U	U		9/27/2024	N				101978	
3944 RIDGELAND AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				101982	
4200 GUNDERSON AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	L	L		9/27/2024	N				101990	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
6503 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				101994	
4104 WENONAH AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				101997	
7025 W. 43 RD ST	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102000	
4446 S GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102001	
4117 HOME AVENUE	N/A	N	N	1988	1988		U	U	U	U		9/27/2024	N				102013	
3932 CLINTON AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				102014	
4430 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102016	
4231 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				102017	
4021 EAST AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102023	
4212 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102028	
4102 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102030	
4100 WISCONSIN AVENUE	LC1T015	N	N	1986	1986	Other - Sample Site	U	L	L	L		9/27/2024	N				102032	
4101 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102033	
7048 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				102034	
4208 SCOVILLE AVENUE	N/A	N	N	2000	2000	Visual Inspection	C	C	C	NL		N/R	N				102036	
4204 RIDGELAND AVENUE	N/A	N	N	1944	1944		U	U	U	U		9/27/2024	N				102037	
4214 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102046	
4224 RIDGELAND AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				102048	
3914 SCOVILLE AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				102049	
4431 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				102051	
4229 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102053	
4425 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				102055	
4145 HOME AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				102060	
7008 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				102064	
4336 HOME AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				102066	
4043 HARLEM AVENUE	N/A	N	N	2023	2023		U	U	U	U		9/27/2024	N				102073	
4215 MAPLE AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				102074	
6610 41ST STREET	N/A	N	N	1997	1997		U	U	U	U		9/27/2024	N				102076	
4034 CLINTON AVENUE	N/A	N	N	2000	2000	Visual Inspection	C	C	C	NL		N/R	N				102090	
4137 SCOVILLE AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				102091	
4353 GROVE AVENUE	LC1T016	N	N	1955	1955	Visual Inspection	U	L	L	L		9/27/2024	N				102092	
4127 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				102094	
4223 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102095	
4007 OAK PARK AVENUE	N/A	N	N	1981	1981		U	U	U	U		9/27/2024	N				102110	
3933 EUCLID AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				102111	
3916 EAST AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				102114	
7108 43RD STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102115	
3923 EAST AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				102133	
4230 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				102136	
4436 MAPLE AVENUE	N/A	N	N	1998	1998		U	U	U	U		9/27/2024	N				102139	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4213 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102141	
4341 CLINTON AVENUE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				102142	
4223 HOME AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N				102143	
4014 EAST AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102144	
4017 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102145	
4334 GROVE AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				102154	
4233 HOME AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102155	
3940 CLARENCE AVENUE	N/A	N	N	1940	1940		U	U	U	U		9/27/2024	N				102156	
4014 RIDGELAND AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102159	
4112 GROVE AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				102160	
4112 CLINTON AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102162	
7030 43RD STREET	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				102164	
3939 EUCLID AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				102165	
7129 40TH PLACE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				102166	
4115 GROVE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				102170	
3911 WESLEY AVENUE	N/A	N	N	1914	1914		U	U	U	U		9/27/2024	N				102171	
4430 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102175	
4214 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102180	
5041 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				102182	
3936 HOME AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				102187	
7109 40TH STREET	N/A	N	N	1975	1975		U	U	U	U		9/27/2024	N				102188	
4018 SCOVILLE AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102192	
3908 HOME AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				102198	
4142 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102200	
4100 EAST AVENUE	N/A	N	N	1994	1994	Visual Inspection	C	C	C	NL		N/R	N				102202	
4313 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				102205	
4018 RIDGELAND AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				102206	
4455 HARLEM AVENUE	N/A	N	N	1999	1999		U	U	U	U		9/27/2024	N				102207	
4455 HARLEM AVE	N/A	N	N	1999	1999		U	U	U	U		9/27/2024	N				102208	
4455 HARLEM AVE	N/A	N	N	1999	1999		U	U	U	U		9/27/2024	N				102209	
4455 HARLEM AVE	N/A	N	N	1999	1999		U	U	U	U		9/27/2024	N				102210	
4455 HARLEM AVE UNIT 3N	N/A	N	N	1999	1999		U	U	U	U		9/27/2024	N				102211	
4453 HARLEM AVENUE	N/A	N	N	2000	2000		U	U	U	U		9/27/2024	N				102213	
4453 HARLEM AVE	N/A	N	N	2000	2000		U	U	U	U		9/27/2024	N				102214	
4453 HARLEM AVE UNIT 3S	N/A	N	N	1999	1999		U	U	U	U		9/27/2024	N				102215	
4453 HARLEM AVENUE	N/A	N	N	1999	1999		U	U	U	U		9/27/2024	N				102216	
4453 HARLEM AVENUE	N/A	N	N	2000	2000		U	U	U	U		9/27/2024	N				102217	
4453 HARLEM AVE	N/A	N	N	2000	2000		U	U	U	U		9/27/2024	N				102218	
4016 GROVE AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				102229	
4425 GROVE AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				102236	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
7127 40TH STREET	N/A	N	N	1922	1922		U	U	U	U		9/27/2024	N					102238
7112 41ST STREET	N/A	N	N	1917	1917		U	U	U	U		9/27/2024	N					102245
4111 SCOVILLE AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N					102250
4107 MAPLE AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N					102254
4044 GROVE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N					102255
3913 ELMWOOD AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N					102256
6637 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N					102257
3946 GUNDERSON AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N					102260
7125 40TH PLACE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					102262
4205 WISCONSIN AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N					102264
4208 GROVE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					102265
4128 WENONAH AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N					102269
4012 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N					102272
4319 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					102273
4013 WESLEY AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N					102275
4225 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					102279
7022 41ST STREET	LC1T013	N	N	1942	1942	Other - Sample Site	U	L	L	L		9/27/2024	N					102284
4329 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N					102290
4102 OAK PARK AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N					102291
4228 RIDGELAND AVENUE	N/A	N	N	1999	1999	Visual Inspection	C	C	C	NL		N/R	N					102292
6933 PERSHING ROAD	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N					102294
4129 1/2 WISCONSIN AVENUE	N/A	N	N	2002	2002	Visual Inspection	C	C	C	NL		N/R	N					102300
4124 CLINTON AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N					102305
4318 WISCONSIN AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N					102311
3915 EAST AVENUE	N/A	N	N	1955	1955	Visual Inspection	U	U	C	U		12/15/2025	N					102314
4212 SCOVILLE AVENUE	N/A	N	N	1916	1916		U	U	U	U		9/27/2024	N					102317
4245 GUNDERSON AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N					102322
5050 39TH STREET	N/A	N	N				U	U	U	U		9/27/2024	N					102326
4111 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N					102327
7044 40TH PLACE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N					102328
4137 ELMWOOD AVENUE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N					102329
4325 HOME AVENUE	N/A	N	N	1993	1993	Visual Inspection	C	C	C	NL		N/R	N					102336
4338 S KENILWORTH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					102337
7014 40TH PLACE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N					102339
4111 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N					102340
4110 CLINTON AVENUE	N/A	N	N	1954	1954	Visual Inspection	U	U	C	U		12/15/2025	N					102341
4036 RIDGELAND AVENUE	LC1T036	N	N	1956	1956	Other - Sample Site	U	L	L	L		9/27/2024	N					102342
3909 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					102345
6901 43RD STREET	LC1T042 - INACTIVE	N	N	1992	1992	Other - Sample Site	U	L	L	L		9/27/2024	N					102347
4141 GUNDERSON AVENUE	N/A	N	N	1913	1913		U	U	U	U		9/27/2024	N					102348

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4301 MAPLE AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				102350	
4336 WISCONSIN AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				102351	
4205 SCOVILLE AVENUE	N/A	N	N	1921	1921		U	U	U	U		9/27/2024	N				102353	
4443 KENILWORTH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102354	
4420 OAK PARK AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102356	
6727 PERSHING ROAD	N/A	N	N			Visual Inspection	U	U	L	L		9/27/2024	N				102361	
4005 GUNDERSON AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				102362	
7119 40TH PLACE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102364	
6641 41ST STREET	N/A	N	N	1979	1979		U	U	U	U		9/27/2024	N				102369	
7028 LORRAINE TERRACE	N/A	N	N	1950	1950	Visual Inspection	U	U	L	L		9/27/2024	N				102370	
4317 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				102372	
6921 43RD STREET	N/A	N	N	1954	1954	Visual Inspection	U	U	C	U		9/27/2024	N				102374	
4219 ELMWOOD AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				102379	
4132 OAK PARK AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102385	
4208 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102391	
3943 WESLEY AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				102394	
4117 GROVE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102399	
4310 WISCONSIN AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				102400	
7018 41ST STREET	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				102401	
7118 40TH PLACE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102402	
4223 MAPLE AVENUE	N/A	N	N	1920	1920		U	U	U	U		9/27/2024	N				102403	
4118 GROVE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102406	
6701 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				102407	
6623 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				102410	
4138 HOME AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				102414	
4124 ELMWOOD AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N				102415	
3914 OAK PARK AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102419	
4208 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102420	
3901 HOME AVENUE	LC1T041	N	N	1950	1950	Other - Sample Site	U	L	L	L		9/27/2024	N				102427	
4118 RIDGELAND AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102436	
4107 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102438	
4436 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102439	
4216 WISCONSIN AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102446	
6611 PERSHING ROAD	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102447	
4220 OAK PARK AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				102449	
4115 SCOVILLE AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				102452	
5030 39TH STREET	N/A	N	N				U	U	U	U		9/27/2024	N				102455	
7029 40TH PLACE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102459	
4332 WISCONSIN AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				102461	
6429 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				102462	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4434 OAK PARK AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N				102463	
3928 EUCLID AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102466	
3913 OAK PARK AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				102468	
4316 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102469	
3931 OAK PARK AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102471	
4213 GROVE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102472	
3940 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102474	
4207 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102476	
4207 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				102482	
7036 40TH STREET	N/A	N	N	1947	1947	Visual Inspection	U	U	L	L		9/27/2024	N				102484	
7033 40TH PLACE	N/A	N	N	1916	1916	Visual Inspection	U	U	L	L		9/27/2024	N				102488	
6426 41ST STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102492	
4303 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				102493	
3936 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102494	
4415 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102498	
3932 RIDGELAND AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				102500	
6831 43RD STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102508	
3940 OAK PARK AVENUE	N/A	N	N	1909	1909		U	U	U	U		9/27/2024	N				102510	
4211 GROVE AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				102512	
4019 EUCLID AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				102516	
7036 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				102517	
3920 HOME AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				102519	
3923 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102521	
3908 GUNDERSON AVENUE	N/A	N	N			Visual Inspection	U	U	C	U		9/27/2024	N				102523	
6600 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102526	
4219 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102530	
4429 HOME AVENUE	N/A	N	N	1955	1955	Visual Inspection	U	U	C	U		12/15/2025	N				102534	
6415 41ST STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102540	
4108 WISCONSIN AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				102542	
4205 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102549	
4203 ELMWOOD AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102552	
4000 RIDGELAND AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102553	
4344 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102554	
4102 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102555	
6433 41ST STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102556	
4445 WISCONSIN AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102561	
4400 GROVE AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				102566	
4204 OAK PARK AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				102568	
4119 GROVE AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				102570	
4014 OAK PARK AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102574	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
7100 40TH STREET	N/A	N	N	1948	1948		U	U	U	U		9/27/2024	N				102576	
4120 ELMWOOD AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				102577	
7019 40TH STREET	N/A	N	N	1979	1979		U	U	U	U		9/27/2024	N				102578	
3927 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102580	
4217 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				102581	
4220 WENONAH AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				102586	
3940 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102587	
7136 40TH PLACE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				102590	
4145 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102601	
4314 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102609	
4027 CLINTON AVENUE	N/A	N	N	1919	1919	Visual Inspection	U	U	L	L		9/27/2024	N				102611	
7025 40TH PLACE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102624	
6505 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				102626	
4213 GUNDERSON AVENUE	N/A	N	N	2003	2003	Visual Inspection	C	C	C	NL		N/R	N				102628	
4141 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102631	
7053 40TH STREET	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				102632	
7017 40TH PLACE	N/A	N	N	1977	1977		U	U	U	U		9/27/2024	N				102636	
4027 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102638	
4106 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102640	
4232 ELMWOOD AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				102641	
4014 SCOVILLE AVENUE	N/A	N	N	1979	1979		U	U	U	U		9/27/2024	N				102642	
7024 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102647	
6621 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				102648	
4442 GROVE AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				102649	
4200 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102654	
4407 WISCONSIN AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				102657	
4004 CLARENCE AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				102660	
4137 MAPLE AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				102661	
3920 SCOVILLE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102663	
6620 41ST STREET	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				102664	
4135 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				102670	
4211 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102672	
3937 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				102681	
4411 WISCONSIN AVENUE	N/A	N	N	2006	2006	Visual Inspection	C	C	C	NL		N/R	N				102685	
4023 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102687	
4109 GROVE AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				102689	
4141 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102690	
4209 GUNDERSON AVENUE	N/A	N	N	2005	2005	Visual Inspection	C	C	C	NL		N/R	N				102693	
4020 CLARENCE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102701	
3937 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102709	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
3930 OAK PARK AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				102711	
4209 MAPLE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102712	
4995 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				102714	
4324 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102715	
4209 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102720	
7009 43RD STREET	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				102721	
4036 OAK PARK AVENUE	N/A	N	N	1998	1998	Visual Inspection	C	C	C	NL		N/R	N				102722	
4130 GROVE AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102723	
7104 43RD STREET	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				102726	
4107 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				102727	
4223 ELMWOOD AVENUE	N/A	N	N	1994	1994	Visual Inspection	C	C	C	NL		N/R	N				102732	
7049 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				102733	
4018 OAK PARK AVENUE	N/A	N	N	1993	1993	Visual Inspection	C	C	C	NL		N/R	N				102734	
4111 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				102735	
4025 CLINTON AVENUE	N/A	N	N	1914	1914		U	U	U	U		9/27/2024	N				102738	
4237 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102744	
4112 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				102748	
4311 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				102750	
3933 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				102754	
4038 CLARENCE AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N				102756	
3933 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102759	
4240 MAPLE AVENUE	N/A	N	N	1973	1973		U	U	U	U		9/27/2024	N				102763	
4227 HOME AVENUE	N/A	N	N	1986	1986		U	U	U	U		9/27/2024	N				102765	
4405 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102778	
4133 MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102779	
3917 EUCLID AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102794	
7015 40TH STREET	N/A	N	N	2005	2005	Visual Inspection	C	C	C	NL		N/R	N				102797	
4332 CLINTON AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				102799	
4019 ELMWOOD AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				102804	
6713 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				102807	
7048 41ST STREET	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				102808	
4117 WISCONSIN AVENUE	N/A	N	N	1958	1958	Visual Inspection	U	U	C	U		9/27/2024	N				102809	
4342 WISCONSIN AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				102812	
4041 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				102815	
3917 SCOVILLE AVENUE	N/A	N	N	1932	1932		U	U	U	U		9/27/2024	N				102818	
4439 WENONAH	N/A	N	N	1995	1995	Visual Inspection	C	C	C	NL		N/R	N				102822	
4008 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102826	
6722 41ST STREET	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				102828	
4426 GROVE AVENUE	N/A	N	N	1986	1986		U	U	U	U		9/27/2024	N				102830	
4236 S RIDGELAND AVENUE	N/A	N	N	1965	1965		U	U	U	U		9/27/2024	N				102839	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
3937 OAK PARK AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				102845	
7021 40TH PLACE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				102859	
3926 S EUCLID AVENUE	N/A	N	N	1948	1948		U	U	U	U		9/27/2024	N				102867	
4330 HOME AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				102868	
4130 ELMWOOD AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				102869	
4220 GROVE AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				102870	
3925 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102871	
4140 ELMWOOD AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				102872	
5001 W 40TH STREET	N/A	N	N				U	U	U	U		9/27/2024	N				102874	
4431 WISCONSIN AVENUE	N/A	N	N	2007	2007	Visual Inspection	C	C	C	NL		N/R	N				102877	
4142 OAK PARK AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				102879	
4030 EUCLID AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				102881	
4134 RIDGELAND AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				102884	
4218 RIDGELAND AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				102885	
4425 WENONAH AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				102887	
7122 43RD STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102889	
4323 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				102892	
4033 OAK PARK AVENUE	N/A	N	N	2002	2002	Visual Inspection	C	C	C	NL		N/R	N				102899	
4323 GROVE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				102901	
3924 CLINTON AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				102904	
4452 GROVE AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	C	U		9/27/2024	N				102905	
4243 ELMWOOD AVENUE	N/A	N	N	2006	2006	Visual Inspection	C	C	C	NL		N/R	N				102907	
4320 OAK PARK AVENUE	N/A	N	N	1948	1948		U	U	U	U		9/27/2024	N				102916	
3923 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				102923	
3935 EAST AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102924	
7026 40TH PLACE	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				102928	
4428 OAK PARK AVENUE	N/A	N	N	1987	1987		U	U	U	U		9/27/2024	N				102932	
4217 WISCONSIN AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				102936	
4225 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102938	
7022 40TH PLACE	N/A	N	N	1933	1933		U	U	U	U		9/27/2024	N				102939	
4142 WISCONSIN AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				102940	
4114 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U		9/27/2024	N				102943	
4018 CLINTON AVENUE	N/A	N	N	2006	2006	Visual Inspection	C	C	C	NL		N/R	N				102945	
4131 WENONAH AVENUE	N/A	N	N	1955	1955	Visual Inspection	U	U	C	U		9/27/2024	N				102949	
7023 43RD STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				102951	
4021 OAK PARK AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				102959	
3925 OAK PARK AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				102972	
4332 RIDGELAND AVENUE	N/A	N	N	2006	2006	Visual Inspection	C	C	C	NL		N/R	N				102974	
4313 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				102977	
4129 MAPLE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				102981	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
7042 43RD STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				102984	
4339 S GROVE AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				102988	
4142 S CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				102990	
4215 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				102993	
4017 HOME AVENUE	N/A	N	N	1933	1933		U	U	U	U		9/27/2024	N				102997	
4153 MAPLE AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103002	
4210 HOME AVENUE	N/A	N	N	1948	1948		U	U	U	U		9/27/2024	N				103004	
4315 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103007	
4346 GROVE AVENUE	N/A	N	N	1946	1946	Visual Inspection	U	U	L	L		9/27/2024	N				103009	
4409 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103010	
4404 MAPLE AVENUE	N/A	N	N	1987	1987		U	U	U	U		9/27/2024	N				103011	
4234 S RIDGELAND AVENUE	N/A	N	N	2005	2005	Visual Inspection	C	C	C	NL		N/R	N				103013	
4142 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103014	
6603 PERSHING ROAD	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				103023	
6601 PERSHING ROAD	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				103024	
4327 WENONAH AVENUE	N/A	N	N	2002	2002	Visual Inspection	C	C	C	NL		N/R	N				103025	
7014 41ST STREET	N/A	N	N	1913	1913		U	U	U	U		9/27/2024	N				103028	
4235 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103031	
6507 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				103032	
3931 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103035	
4313 KENILWORTH AVENUE	N/A	N	N	1966	1966		U	U	U	U		9/27/2024	N				103038	
6733 PERSHING ROAD	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				103039	
7026 43RD STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103040	
4404 KENILWORTH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103041	
4144 S MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103047	
4209 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103049	
7033 43RD STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103051	
4215 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103052	
4414 MAPLE AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				103058	
4118 GUNDERSON AVE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				103060	
4309 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103061	
4350 GROVE AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				103062	
4216 SCOVILLE AVENUE	N/A	N	N	1933	1933		U	U	U	U		9/27/2024	N				103063	
3914 CLARENCE AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103064	
4128 GROVE AVENUE	N/A	N	N	1965	1965		U	U	U	U		9/27/2024	N				103067	
4041 GROVE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103068	
4012 S SCOVILLE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				103072	
4201 CLINTON AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				103073	
4111 S GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103079	
6001 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				103081	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section	Water System Name		Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026						
*Please enter totals in the empty box next to each category	Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:	https://lead-service-line-inventory-1-novotny.hub.arcgis.com/					
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4209 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103082	
4217 CLINTON AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				103083	
4045 GROVE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103084	
6412 41ST STREET	N/A	N	N	1955	1955	Visual Inspection	U	U	C	U		9/27/2024	N				103085	
6919 43RD STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103086	
4304 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				103089	
7001 40TH STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103090	
7120 41ST STREET	N/A	N	N	1917	1917		U	U	U	U		9/27/2024	N				103092	
4119 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103096	
4121 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103097	
4233 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103101	
4032 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103104	
4115 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103105	
4223 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				103108	
4320 KENILWORTH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103109	
3948 ELMWOOD AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				103115	
6740 41ST STREET	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				103116	
4421 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U		9/27/2024	N				103117	
4228 ELMWOOD AVENUE	N/A	N	N	1972	1972		U	U	U	U		9/27/2024	N				103125	
4230 ELMWOOD AVENUE	N/A	N	N	1935	1935		U	U	U	U		9/27/2024	N				103127	
6517 W 41ST STREET	N/A	N	N	1958	1958	Visual Inspection	U	U	C	U		9/27/2024	N				103129	
4039 GROVE AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				103131	
4100 MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103136	
7029 PERSHING ROAD	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103138	
4309 KENILWORTH AVENUE	N/A	N	N	1966	1966	Visual Inspection	U	U	C	U		9/27/2024	N				103144	
4418 MAPLE AVENUE	N/A	N	N	1942	1942		U	U	U	U		9/27/2024	N				103146	
4025 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103148	
4040 GUNDERSON AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N				103149	
4001 EAST AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N				103152	
4229 GUNDERSON AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103153	
6435 41ST STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103154	
4207 WISCONSIN AVENUE	N/A	N	N	1933	1933		U	U	U	U		9/27/2024	N				103158	
7012 40TH PLACE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N				103160	
4213 EAST AVENUE	N/A	N	N	1957	1957	Visual Inspection	C	C	C	NL		N/R	N				103163	
4210 MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103164	
4212 GUNDERSON AVENUE	N/A	N	N	1955	1955	Visual Inspection	U	U	C	U		12/15/2025	N				103166	
4030 EAST AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				103167	
6923 43RD STREET	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				103170	
3918 CLINTON AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				103175	
4017 ELMWOOD AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				103177	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4102 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103178	
4122 RIDGELAND AVENUE	N/A	N	N	1956	1956	Visual Inspection	U	U	C	U		9/27/2024	N				103180	
4126 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103186	
4020 RIDGELAND AVENUE	N/A	N	N	1921	1921		U	U	U	U		9/27/2024	N				103187	
4221 WENONAH AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				103191	
4037 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103192	
4033 EAST AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103193	
4301 HOME AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103194	
4997 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				103196	
4350 WENONAH AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103197	
4338 GROVE AVENUE	N/A	N	N	1947	1947	Visual Inspection	U	U	L	L		9/27/2024	N				103199	
4200 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103200	
3939 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103203	
7005 40TH STREET	N/A	N	N	1953	1953	Visual Inspection	U	U	L	L		9/27/2024	N				103204	
4022 OAK PARK AVENUE	N/A	N	N	1997	1997	Visual Inspection	C	C	C	NL		N/R	N				103206	
4226 RIDGELAND AVENUE	N/A	N	N	1941	1941	Visual Inspection	U	U	L	L		9/27/2024	N				103207	
6526 41ST STREET	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				103208	
3909 HOME AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103209	
4010 GUNDERSON AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				103211	
3935 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103212	
4024 OAK PARK AVENUE	N/A	N	N	1997	1997	Visual Inspection	C	C	C	NL		N/R	N				103214	
3928 CLINTON AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				103215	
4416 WISCONSIN AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103218	
4019 EAST AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103221	
4319 GROVE AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				103224	
7018 43RD STREET	N/A	N	N	1934	1934		U	U	U	U		9/27/2024	N				103227	
4332 OAK PARK AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				103228	
4326 KENILWORTH AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103232	
3928 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103233	
4148 WISCONSIN AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103238	
3928 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103240	
7045 43RD STREET	N/A	N	N	1955	1955	Visual Inspection	U	U	C	U		12/15/2025	N				103243	
3925 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103244	
3925 WESLEY AVENUE	N/A	N	N	1954	1954	Visual Inspection	U	U	L	L		9/27/2024	N				103245	
4104 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103250	
3915 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103251	
4204 WENONAH AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103252	
7123 40TH PLACE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103253	
7034 40TH PLACE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103256	
3909 WISCONSIN AVENUE	N/A	N	N	1949	1949	Visual Inspection	U	U	L	L		9/27/2024	N				103257	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned Service Line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4211 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103261	
6432 41ST STREET	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				103263	
4244 SCOVILLE AVENUE	N/A	N	N	1914	1914		U	U	U	U		9/27/2024	N				103264	
4206 WISCONSIN AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103265	
7023 40TH STREET	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				103267	
6504 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103269	
4138 ELMWOOD AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				103270	
4016 SCOVILLE AVENUE	N/A	N	N	1981	1981		U	U	U	U		9/27/2024	N				103271	
4432 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103272	
4406 WENONAH AVENUE	N/A	N	N	1954	1954	Visual Inspection	U	U	C	U		9/27/2024	N				103273	
4106 WISCONSIN AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				103276	
4435 WISCONSIN AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103278	
4019 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103279	
4137 GROVE AVENUE	N/A	N	N	1930	1930	Visual Inspection	U	U	L	L		9/27/2024	N				103280	
4042 OAK PARK AVENUE	N/A	N	N	1923	1923		U	U	U	U		9/27/2024	N				103281	
4044 OAK PARK AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103282	
4215 GROVE AVENUE	N/A	N	N	1976	1976		U	U	U	U		9/27/2024	N				103285	
4111 ELMWOOD AVENUE	N/A	N	N	1923	1923		U	U	U	U		9/27/2024	N				103286	
4017 GUNDERSON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103288	
3922 OAK PARK AVENUE	N/A	N	N	1924	1924	Visual Inspection	U	U	L	L		9/27/2024	N				103292	
3928 GUNDERSON AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N				103295	
3920 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103296	
4424 GROVE AVENUE	N/A	N	N	1968	1968		U	U	U	U		9/27/2024	N				103297	
4035 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103298	
3924 EUCLID AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N				103299	
4326 CLINTON AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				103303	
4118 OAK PARK AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103304	
4347 GROVE AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103305	
4225 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				103307	
7037 40TH STREET	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103311	
4025 OAK PARK AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103314	
4117 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103315	
4028 GUNDERSON AVENUE	N/A	N	N	1914	1914		U	U	U	U		9/27/2024	N				103316	
3916 OAK PARK AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				103318	
4111 MAPLE AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				103319	
6915 43RD STREET	N/A	N	N	2007	2007	Visual Inspection	C	C	C	NL		N/R	N				103320	
4022 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103323	
3913 WENONAH AVENUE	N/A	N	N	1949	1949	Visual Inspection	U	U	L	L		9/27/2024	N				103325	
6510 41ST STREET	LC1T011	N	N	1989	1989	Other - Sample Site	U	L	L	L		9/27/2024	N				103327	
3927 OAK PARK AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103328	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4421 HARLEM AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N					103329
4029 EUCLID AVENUE	N/A	N	N	2011	2011	Visual Inspection	C	C	C	NL		N/R	N					103330
7132 41ST STREET	N/A	N	N	1994	1994	Visual Inspection	C	C	C	NL		N/R	N					103332
3927 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N					103333
4238 SCOVILLE AVENUE	N/A	N	N	1940	1940		U	U	U	U		9/27/2024	N					103335
3917 GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N					103336
4242 SCOVILLE AVENUE	N/A	N	N	1909	1909		U	U	U	U		9/27/2024	N					103338
4446 MAPLE AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N					103339
4233 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N					103341
4403 MAPLE AVENUE	N/A	N	N	1935	1935		U	U	U	U		9/27/2024	N					103342
4104 MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					103343
4118 WENONAH AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N					103344
6728 41ST STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					103346
4204 MAPLE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N					103347
4022 CLARENCE AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N					103349
4022 GUNDERSON AVENUE	N/A	N	N	1938	1938		U	U	U	U		9/27/2024	N					103352
4326 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N					103354
4037 HOME AVENUE	N/A	N	N	1997	1997	Visual Inspection	C	C	C	NL		N/R	N					103355
4125 WENONAH AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	C	U		9/27/2024	N					103358
4001 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N					103359
6507 41ST STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					103362
3936 OAK PARK AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N					103363
4218 MAPLE AVENUE	N/A	N	N	1923	1923		U	U	U	U		9/27/2024	N					103364
4333 WISCONSIN AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N					103366
4306 WISCONSIN AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N					103367
3945 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N					103368
6518 41ST STREET	N/A	N	N	2000	2000	Visual Inspection	C	C	C	NL		N/R	N					103369
3900 OAK PARK AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N					103372
6737 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N					103376
4135 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					103377
3920 GROVE AVENUE	N/A	N	N	1924	1924	Visual Inspection	U	U	L	L		9/27/2024	N					103378
6423 41ST STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N					103380
7109 PERSHING ROAD	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N					103382
4141 MAPLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N					103383
4201 GUNDERSON AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N					103387
4143 SCOVILLE AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N					103390
3921 HOME AVENUE	N/A	N	N	1899	1899		U	U	U	U		9/27/2024	N					103394
6715 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N					103395
4114 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					103396
4144 GROVE AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N					103398

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LX". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned Service Line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4324 WENONAH AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103399	
4315 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				103400	
7045 40TH PLACE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103401	
3900 LARAMIE AVE	N/A	N	N				U	U	U	U		9/27/2024	N				103403	
4031 HARLEM AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103404	
4436 WISCONSIN AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103408	
4444 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103410	
4224 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103413	
6735 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				103414	
4146 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103420	
3923 GUNDERSON AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				103421	
4445 MAPLE AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				103422	
4440 WENONAH AVENUE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				103423	
4137 CLINTON AVENUE	N/A	N	N	1950	1950	Visual Inspection	U	U	C	U		9/27/2024	N				103424	
7008 40TH PLACE	N/A	N	N	1993	1993	Visual Inspection	C	C	C	NL		N/R	N				103425	
7016 43RD STREET	N/A	N	N	1940	1940		U	U	U	U		9/27/2024	N				103426	
4242 GUNDERSON AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				103428	
4021 GUNDERSON AVENUE	N/A	N	N	1940	1940		U	U	U	U		9/27/2024	N				103430	
4104 EAST AVENUE	N/A	N	N			Visual Inspection	C	C	C	NL		N/R	N				103431	
4015 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103432	
4240 S SCOVILLE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103435	
4147 CLINTON AVENUE	N/A	N	N	1966	1966		U	U	U	U		9/27/2024	N				103436	
4111 S GUNDERSON AVENUE	N/A	N	N	1918	1918		U	U	U	U		9/27/2024	N				103438	
4031 WESLEY AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103441	
4344 OAK PARK AVENUE	N/A	N	N	1948	1948		U	U	U	U		9/27/2024	N				103443	
4339 KENILWORTH AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103444	
4242 ELMWOOD AVENUE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				103445	
4317 S WENONAH AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				103446	
6612 W 41ST STREET	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				103447	
4113 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103448	
4436 OAK PARK AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103451	
4033 S SCOVILLE AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				103452	
4341 HOME AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				103453	
4028 EAST AVENUE	N/A	N	N	1990	1990	Visual Inspection	C	C	C	NL		N/R	N				103454	
4227 S WISCONSIN AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				103457	
4005 S CLINTON AVENUE	LC11028	N	N	1926	1926	Other - Sample Site	U	L	L	L		9/27/2024	N				103458	
4301 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103459	
4035 ELMWOOD AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				103460	
7032 W 43RD STREET	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				103461	
7131 W 40TH PLACE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103462	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned Service Line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (D) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (D) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (D) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (D) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4123 S GUNDERSON AVENUE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				103463	
4220 RIDGELAND AVENUE	N/A	N	N	2009	2009	Visual Inspection	C	C	C	NL		N/R	N				103464	
4016 CLARENCE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103465	
7017 W 40TH STREET	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				103466	
3928 SCOVILLE AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				103468	
4240 GROVE AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				103469	
4024 S CLINTON AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				103470	
4101 S MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				103473	
4437 WISCONSIN AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103474	
4343 WISCONSIN AVENUE	N/A	N	N			Visual Inspection	U	U	C	U		12/15/2025	N				103475	
4040 S GROVE AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N				103476	
7104 W 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				103479	
4319 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103482	
4321 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103483	
4033 WESLEY AVENUE	LC1T030	N	N	1924	1924	Other - Sample Site	U	L	L	L		9/27/2024	N				103485	
4144 S RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103486	
4216 GUNDERSON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103487	
4439 MAPLE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				103488	
3912 SCOVILLE AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				103489	
4139 S WISCONSIN AVENUE	N/A	N	N	1972	1972		U	U	U	U		9/27/2024	N				103491	
4424 CLINTON AVENUE	LC1T043 - INACTIVE	N	N	1989	1989	Other - Sample Site	U	L	L	L		9/27/2024	N				103493	
4204 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103494	
4128 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103497	
4219 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103498	
4221 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103499	
4201 S HOME AVENUE	N/A	N	N	2012	2012		U	U	U	U		9/27/2024	N				103500	
3946 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103501	
3933 S CLARENCE AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103502	
7100 43RD STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103503	
4016 S GUNDERSON AVENUE	N/A	N	N	1917	1917		U	U	U	U		9/27/2024	N				103506	
4041 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103507	
4207 GROVE AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				103509	
4329 S HOME AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				103510	
3933 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103514	
3917 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103517	
4122 OAK PARK AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103518	
4118 MAPLE AVENUE	N/A	N	N	1975	1975		U	U	U	U		9/27/2024	N				103519	
4141 S CLINTON AVENUE	N/A	N	N	1950	1950	Visual Inspection	U	U	C	U		9/27/2024	N				103521	
4405 S HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103522	
3937 EUCLID AVENUE	N/A	N	N	1936	1936		U	U	U	U		9/27/2024	N				103523	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4025 GUNDERSON AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N				103524	
3925 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	U	L		9/27/2024	N				103528	
4239 GUNDERSON AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103530	
4006 WESLEY AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				103532	
7101 40TH STREET	N/A	N	N	1941	1941		U	U	U	U		9/27/2024	N				103533	
7021 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	U	L		9/27/2024	N				103538	
4031 OAK PARK AVENUE	N/A	N	N	2002	2002	Visual Inspection	C	C	C	NL		N/R	N				103539	
4026 S OAK PARK AVENUE	N/A	N	N	2000	2000	Visual Inspection	C	C	C	NL		N/R	N				103541	
4008 CLARENCE AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				103542	
4005 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103544	
4116 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103546	
7002 W 40TH PLACE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				103547	
4128 ELMWOOD AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				103550	
3939 EAST AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103551	
3920 ELMWOOD AVENUE	N/A	N	N	1929	1929	Visual Inspection	U	U	C	U		9/27/2024	N				103552	
4120 GUNDERSON AVENUE	N/A	N	N	1919	1919	Visual Inspection	U	U	L	L		9/27/2024	N				103554	
7133 W 40TH PLACE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				103556	
4144 S ELMWOOD AVENUE	N/A	N	N	1922	1922		U	U	U	U		9/27/2024	N				103558	
4350 OAK PARK AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103559	
4028 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103561	
7053 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103562	
4316 OAK PARK AVENUE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				103563	
4320 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				103565	
4427 CLINTON AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				103566	
4200 S GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103567	
4226 ELMWOOD AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103569	
4212 RIDGELAND AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N				103571	
4241 GROVE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103573	
4111 WENONAH AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103576	
3938 OAK PARK AVENUE	N/A	N	N	1928	1928	Visual Inspection	U	U	L	L		9/27/2024	N				103577	
7007 40TH STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103579	
7039 40TH PLACE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				103580	
7103 40TH PLACE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				103581	
4235 EAST AVENUE	N/A	N	N	1961	1961	Visual Inspection	C	C	C	NL		N/R	N				103583	
4140 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103585	
3905 HOME AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103588	
4444 KENILWORTH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103591	
4108 EAST AVENUE	N/A	N	N	1993	1993	Visual Inspection	C	C	C	NL		N/R	N				103593	
4441 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103596	
4321 HOME AVENUE	N/A	N	N	1937	1937		U	U	U	U		9/27/2024	N				103598	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
6832 43RD STREET	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103599	
4320 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103600	
4419 CLINTON AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				103602	
4205 HARLEM AVENUE	N/A	N	N	1996	1996	Visual Inspection	C	C	C	NL		N/R	N				103603	
3921 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103604	
4045 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103605	
4436 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103606	
4127 S HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103608	
4112 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103610	
6732 W 41ST STREET	N/A	N	N	1938	1938		U	U	U	U		9/27/2024	N				103618	
3936 CLARENCE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				103619	
4228 WISCONSIN AVENUE	N/A	N	N	1952	1952	Visual Inspection	U	U	C	U		12/15/2025	N				103620	
4458 OAK PARK AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103621	
3920 CLINTON AVENUE	LC1T001	N	N	1957	1957	Other - Sample Site	U	L	L	L		9/27/2024	N				103624	
4220 MAPLE AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				103625	
3924 HOME AVENUE	N/A	N	N	1948	1948		U	U	U	U		9/27/2024	N				103627	
7010 43RD STREET	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103629	
4318 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				103630	
4009 CLINTON AVENUE	N/A	N	N	1979	1979		U	U	U	U		9/27/2024	N				103633	
3918 RIDGELAND AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103634	
4115 GUNDERSON AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	C	U		9/27/2024	N				103639	
4402 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103640	
4113 HOME AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103641	
4000 EAST AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				103643	
4426 WISCONSIN AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N				103644	
4340 WISCONSIN AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				103646	
4221 GUNDERSON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103647	
4008 OAK PARK AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103648	
4023 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103649	
4215 CLINTON AVENUE	N/A	N	N	2009	2009	Visual Inspection	C	C	C	NL		N/R	N				103650	
4236 GROVE AVENUE	N/A	N	N	1922	1922		U	U	U	U		9/27/2024	N				103653	
4425 WISCONSIN AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				103654	
4449 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U		9/27/2024	N				103655	
6619 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				103660	
4007 GUNDERSON AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				103661	
4317 WISCONSIN AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				103662	
7043 40TH PLACE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103663	
4131 WISCONSIN AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103664	
4022 EAST AVENUE	N/A	N	N	2005	2005	Visual Inspection	C	C	C	NL		N/R	N				103665	
3916 CLINTON AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				103666	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
3916 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103669	
7031 40TH STREET	N/A	N	N	1973	1973		U	U	U	U		9/27/2024	N				103670	
4007 EAST AVENUE	N/A	N	N	1940	1940		U	U	U	U		9/27/2024	N				103671	
4121 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103673	
6520 41ST STREET	N/A	N	N	1956	1956	Visual Inspection	U	U	C	U		12/15/2025	N				103675	
4029 OAK PARK AVENUE	N/A	N	N	2002	2002	Visual Inspection	C	C	C	NL		N/R	N				103676	
4017 EAST AVENUE	N/A	N	N	1935	1935		U	U	U	U		9/27/2024	N				103678	
7025 LORRAINE TERRACE	N/A	N	N	1954	1954	Visual Inspection	U	U	L	L		9/27/2024	N				103679	
6001 PERSHING RD	N/A	N	N				U	U	U	U		9/27/2024	N				103681	
4122 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103683	
7116 41ST STREET	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				103684	
4133 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103685	
4322 KENILWORTH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103688	
4031 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103689	
3905 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103690	
3945 CLARENCE AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103691	
7134 41ST STREET	N/A	N	N	2008	2008	Visual Inspection	C	C	C	NL		N/R	N				103692	
4212 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103694	
4026 EAST AVENUE	N/A	N	N	1940	1940		U	U	U	U		9/27/2024	N				103695	
3939 OAK PARK AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				103696	
7036 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				103697	
4222 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103701	
4120 MAPLE AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				103703	
4210 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103706	
7016 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				103707	
4322 GROVE AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103709	
3912 WESLEY AVENUE	N/A	N	N	1923	1923		U	U	U	U		9/27/2024	N				103710	
7110 40TH PLACE	N/A	N	N	1999	1999	Visual Inspection	C	C	C	NL		N/R	N				103711	
4207 WENONAH AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				103715	
4449 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103717	
4112 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103718	
7124 41ST STREET	N/A	N	N	1917	1917		U	U	U	U		9/27/2024	N				103719	
4003 EAST AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103721	
4039 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103722	
3941 GROVE AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				103724	
7134 W 43RD STREET	N/A	N	N	2009	2009	Visual Inspection	C	C	C	NL		N/R	N				103725	
4441 S HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103726	
4139 HOME AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				103727	
4007 EUCLID AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N				103728	
6644 W 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103729	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LX". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
6401 W 41ST STREET	LC1T037	N	N	1954	1954	Other - Sample Site	U	L	L	L		9/27/2024	N				103730	
3930 S EAST AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103731	
7127 40TH PLACE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103733	
6436 41ST STREET	N/A	N	N	2005	2005	Visual Inspection	C	C	C	NL		N/R	N				103734	
4201 SCOVILLE AVENUE	LC1T019	N	N	1957	1957	Visual Inspection	U	L	C	L		12/15/2025	N				103735	
3933 OAK PARK AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103737	
4100 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103738	
4022 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103739	
7041 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103741	
4109 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103742	
7037 PERSHING ROAD	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103743	
4444 WISCONSIN AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				103744	
6427 41ST STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103745	
4009 WESLEY AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103747	
3928 HOME AVENUE	N/A	N	N	1948	1948		U	U	U	U		9/27/2024	N				103749	
4144 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103751	
3932 EUCLID AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N				103752	
7116 W 43RD STREET	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103753	
4305 MAPLE AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				103754	
4445 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103755	
4201 GROVE AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				103756	
4328 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103757	
4321 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103758	
4124 OAK PARK AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				103760	
3921 EUCLID AVENUE	N/A	N	N	1923	1923		U	U	U	U		9/27/2024	N				103761	
4229 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103762	
4119 S WISCONSIN AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103765	
4035 GUNDERSON AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				103767	
6513 41ST STREET	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				103768	
4214 OAK PARK AVENUE	N/A	N	N	1955	1955	Visual Inspection	U	U	C	U		9/27/2024	N				103769	
4135 SCOVILLE AVENUE	N/A	N	N	1914	1914		U	U	U	U		9/27/2024	N				103770	
3911 GROVE AVENUE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				103771	
6634 41ST STREET	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				103772	
3917 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103773	
4308 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				103774	
4128 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103775	
4007 SCOVILLE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				103776	
7112 40TH PLACE	N/A	N	N	1915	1915		U	U	U	U		9/27/2024	N				103777	
4030 OAK PARK AVENUE	N/A	N	N	2000	2000	Visual Inspection	C	C	C	NL		N/R	N				103778	
4231 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103779	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4018 GROVE AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103780	
4101 GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103781	
4444 CLINTON AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				103782	
4007 ELMWOOD AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				103783	
4211 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103784	
4402 MAPLE AVENUE	N/A	N	N	1989	1989		U	U	U	U		9/27/2024	N				103787	
4343 WENONAH AVENUE	N/A	N	N	1932	1932		U	U	U	U		9/27/2024	N				103789	
4106 MAPLE AVENUE	N/A	N	N	1922	1922		U	U	U	U		9/27/2024	N				103790	
4030 WESLEY AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				103791	
4220 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103793	
3941 GUNDERSON AVENUE	N/A	N	N	1923	1923		U	U	U	U		9/27/2024	N				103794	
4421 WISCONSIN AVENUE	N/A	N	N	2017	2017	Visual Inspection	C	C	C	NL		N/R	N				103795	
4007 CLINTON AVENUE	N/A	N	N	1934	1934		U	U	U	U		9/27/2024	N				103796	
4430 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U		9/27/2024	N				103797	
4136 S HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103798	
4316 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103802	
4002 WESLEY AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103805	
4100 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103806	
6633 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				103807	
4237 ELMWOOD AVENUE	N/A	N	N	1990	1990	Visual Inspection	C	C	C	NL		N/R	N				103813	
4017 CLARENCE AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				103814	
6615 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				103815	
4208 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103817	
3936 SCOVILLE AVENUE	N/A	N	N	1941	1941		U	U	U	U		9/27/2024	N				103819	
4408 OAK PARK AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103822	
3945 ELMWOOD AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103827	
4132 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103828	
4143 CLINTON AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103829	
4136 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103830	
6929 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				103831	
7128 40TH PLACE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103832	
4450 GROVE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103834	
3916 HOME AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				103835	
6405 W 41ST STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103836	
6708 41ST STREET	N/A	N	Y	1954	1954		U	U	U	U		9/27/2024	N				103838	
6511 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103839	
6929 43RD STREET	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				103840	
6437 41ST STREET	N/A	N	N	1933	1933	Visual Inspection	U	U	U	C		9/27/2024	N				103841	
4432 WENONAH AVENUE	LC1T025	N	N	1953	1953	Other - Sample Site	U	L	L	L		9/27/2024	N				103842	
4020 EAST AVENUE	N/A	N	N	2014	2014	Visual Inspection	C	C	C	NL		N/R	N				103843	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4019 CLINTON AVENUE	N/A	N	N	1999	1999	Visual Inspection	C	C	C	NL		N/R	N					103845
4351 GROVE AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N					103848
7105 40TH PLACE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N					103849
4330 KENILWORTH AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N					103850
4140 OAK PARK AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N					103851
4232 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					103852
4140 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					103853
4123 WISCONSIN AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N					103855
3910 GROVE AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N					103857
4116 HOME AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N					103858
4003 HOME AVENUE	N/A	N	N	1920	1920		U	U	U	U		9/27/2024	N					103859
4216 MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					103860
3934 GROVE AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N					103861
4129 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N					103862
4128 GUNDERSON AVENUE	N/A	N	N	1932	1932		U	U	U	U		9/27/2024	N					103864
4121 GUNDERSON AVENUE	N/A	N	N	1914	1914		U	U	U	U		9/27/2024	N					103865
3937 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					103866
4425 MAPLE AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N					103869
6811 PERSHING ROAD	N/A	N	N	1943	1943		U	U	U	U		9/27/2024	N					103870
3914 ELMWOOD AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N					103873
3912 OAK PARK AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N					103874
4136 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					103875
4231 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					103881
7041 43RD STREET	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N					103882
4334 KENILWORTH AVENUE	N/A	N	N	1988	1988		U	U	U	U		9/27/2024	N					103885
4002 EAST AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N					103886
4240 GUNDERSON AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N					103888
4119 MAPLE AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N					103889
4016 EAST AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					103890
7011 W 40TH PLACE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					103891
4036 GUNDERSON AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N					103892
6607 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N					103893
4201 WENONAH AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N					103895
4337 WISCONSIN AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N					103896
4208 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					103897
7114 41ST STREET	N/A	N	N	1976	1976		U	U	U	U		9/27/2024	N					103898
4231 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					103899
4445 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					103901
4145 MAPLE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					103902
3942 RIDGELAND AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					103903

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4424 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				103904	
4042 GROVE AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103907	
4228 SCOVILLE AVENUE	N/A	N	N	1910	1910		U	U	U	U		9/27/2024	N				103910	
4312 WENONAH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103911	
4222 MAPLE AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				103912	
4322 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				103913	
4031 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103915	
4412 GROVE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103916	
5000 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				103917	
5000 PERSHING RD	N/A	N	N				U	U	U	U		9/27/2024	N				103918	
4226 OAK PARK AVENUE	N/A	N	N	1940	1940		U	U	U	U		9/27/2024	N				103920	
4212 HOME AVENUE	N/A	N	N	1941	1941		U	U	U	U		9/27/2024	N				103922	
6621 41ST STREET	N/A	N	N	1978	1978		U	U	U	U		9/27/2024	N				103923	
3929 WESLEY AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103925	
4139 ELMWOOD AVENUE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				103927	
3756 CICERO AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103928	
4149 MAPLE AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103929	
7035 40TH STREET	N/A	N	N	1968	1968		U	U	U	U		9/27/2024	N				103931	
3944 SCOVILLE AVENUE	N/A	N	N	1918	1918		U	U	U	U		9/27/2024	N				103932	
7019 40TH PLACE	N/A	N	N	1979	1979		U	U	U	U		9/27/2024	N				103934	
4146 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103935	
4312 WISCONSIN AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				103937	
4211 MAPLE AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				103939	
4423 CLINTON AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				103940	
4322 OAK PARK AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				103941	
3924 GROVE AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				103944	
4116 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103946	
4411 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				103947	
4449 HOME AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103948	
3920 WESLEY AVENUE	N/A	N	N	1922	1922		U	U	U	U		9/27/2024	N				103949	
4027 EAST AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				103950	
7013 43RD STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				103951	
3901 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				103952	
7125 40TH STREET	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				103953	
6921 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				103954	
6925 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				103955	
4126 HOME AVENUE	N/A	N	N	1932	1932		U	U	U	U		9/27/2024	N				103957	
4131 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				103959	
3921 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103961	
4323 HOME AVENUE	N/A	N	N	1993	1993	Visual Inspection	C	C	C	NL		N/R	N				103962	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name		Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026					
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned Service Line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.	
4436 KENILWORTH AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103964	
3940 SCOVILLE AVENUE	LC1T033	N	N	1953	1953	Other - Sample Site	U	L	L	L		9/27/2024	N				103965	
3935 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103966	
4024 WESLEY AVENUE	N/A	N	N	1957	1957	Visual Inspection	U	U	C	U		12/15/2025	N				103968	
4142 GROVE AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				103969	
4311 KENILWORTH AVENUE	N/A	N	N	1966	1966	Visual Inspection	U	U	C	U		12/15/2025	N				103971	
3936 WESLEY AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				103972	
4244 CLINTON AVENUE	LC1T023	N	N	1953	1953	Other - Sample Site	U	L	L	L		9/27/2024	N				103973	
3900 WENONAH AVENUE	LC1T032	N	N	1948	1948	Visual Inspection	U	L	L	L		9/27/2024	N				103974	
6524 41ST STREET	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				103976	
4012 GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103978	
3929 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103980	
4352 GROVE AVENUE	N/A	N	N	2005	2005	Visual Inspection	C	C	C	NL		N/R	N				103981	
7011 40TH STREET	N/A	N	N	1981	1981		U	U	U	U		9/27/2024	N				103984	
4423 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				103985	
4140 S WISCONSIN AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				103986	
6911 43RD STREET	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				103987	
3932 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				103988	
7106 40TH PLACE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				103989	
4013 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				103990	
4406 WISCONSIN AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				103991	
7044 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				103992	
4128 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				103993	
4124 WENONAH AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				103994	
4001 CLINTON AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103995	
4225 SCOVILLE AVENUE	N/A	N	N	1965	1965		U	U	U	U		9/27/2024	N				103998	
4134 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				103999	
4028 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104000	
4316 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				104001	
7005 40TH PLACE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				104002	
4222 GROVE AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				104004	
3924 EAST AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104007	
3939 SCOVILLE AVENUE	N/A	N	N	1971	1971		U	U	U	U		9/27/2024	N				104008	
4218 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104009	
4331 GROVE AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				104011	
4025 EUCLID AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104015	
4206 ELMWOOD AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104016	
4023 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104018	
4246 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104019	
4020 GUNDERSON AVENUE	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				104021	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4224 OAK PARK AVENUE	N/A	N	N	1934	1934		U	U	U	U		9/27/2024	N				104023	
4017 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104025	
3927 CLARENCE AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104026	
3925 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				104027	
7111 40TH STREET	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				104029	
4036 GROVE AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				104031	
4141 GROVE AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				104032	
4220 HOME AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				104033	
3916 CLARENCE AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104035	
4325 CLINTON AVENUE	N/A	N	N	1954	1954	Visual Inspection	U	U	U	C		9/27/2024	N				104038	
4116 GUNDERSON AVENUE	N/A	N	N			Visual Inspection	C	C	C	NL		N/R	N				104039	
3800 CICERO AVENUE	N/A	N	N	2023	2023		U	U	U	U		9/27/2024	N				104040	
7021 40TH STREET	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				104041	
4008 GROVE AVENUE	N/A	N	N	1934	1934		U	U	U	U		9/27/2024	N				104042	
4115 MAPLE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				104043	
4244 GUNDERSON AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				104044	
7040 40TH PLACE	N/A	N	N	1984	1984		U	U	U	U		9/27/2024	N				104048	
3925 EAST AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				104049	
3939 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104050	
4139 SCOVILLE AVENUE	N/A	N	N	1939	1939		U	U	U	U		9/27/2024	N				104051	
3916 WESLEY AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				104052	
4034 OAK PARK AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104056	
4126 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104057	
3901 WENONAH AVENUE	N/A	N	N	1949	1949	Visual Inspection	U	U	L	L		9/27/2024	N				104058	
4425 HOME AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				104061	
4242 GROVE AVENUE	N/A	N	N	1923	1923		U	U	U	U		9/27/2024	N				104062	
3922 CLINTON AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				104063	
3934 GUNDERSON AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				104064	
4026 CLARENCE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104065	
3728 CICERO AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				104068	
6439 41ST STREET	N/A	N	N	1997	1997	Visual Inspection	C	C	C	NL		N/R	N				104070	
7041 PERSHING ROAD	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				104071	
6419 41ST STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104072	
4128 WISCONSIN AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				104073	
4004 RIDGELAND AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104074	
4124 GROVE AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104076	
4217 WENONAH AVENUE	N/A	N	N	1986	1986		U	U	U	U		9/27/2024	N				104077	
4008 GUNDERSON AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				104078	
3938 ELMWOOD AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				104079	
4215 GUNDERSON AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104080	

Lead Service Line Inventory Template																									
*Please enter information in the empty box next to each section		Water System Name		Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026												
*Please enter totals in the empty box next to each category		Total Service lines:		1906		Total Lead:		136		Total Non-Lead:		113		Total Galvanized Requiring replacement:		0		Total Unknown:		1657		Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number							
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.								
7104 40TH PLACE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				104082								
4400 KENILWORTH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104083								
4415 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				104085								
3940 GROVE AVENUE	N/A	N	N	1938	1938		U	U	U	U		9/27/2024	N				104086								
7013 40TH STREET	N/A	N	N	1983	1983		U	U	U	U		9/27/2024	N				104087								
4221 SCOVILLE AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				104088								
4024 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104089								
6827 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104090								
4136 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104091								
4400 WISCONSIN AVENUE	N/A	N	N	2017	2017	Visual Inspection	C	C	C	NL		N/R	N				104092								
4009 CLARENCE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104093								
4006 SCOVILLE AVENUE	N/A	N	N	1921	1921		U	U	U	U		9/27/2024	N				104094								
4015 CLARENCE AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				104095								
4032 GROVE AVENUE	LC1T022	N	N	1944	1944	Other - Sample Site	U	L	L	L		9/27/2024	N				104096								
3936 EAST AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	L	L		9/27/2024	N				104098								
4216 RIDGELAND AVENUE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				104099								
4340 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104100								
4202 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104102								
7130 43RD STREET	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				104103								
4000 CLINTON AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				104104								
4235 WENONAH AVENUE	N/A	N	N	1954	1954	Visual Inspection	U	U	C	U		9/27/2024	N				104105								
4206 S GUNDERSON AVENUE	N/A	N	N	2017	2017	Visual Inspection	C	C	C	NL		N/R	N				104107								
4415 HOME AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104108								
4230 RIDGELAND AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N				104109								
3924 CLARENCE AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				104110								
4120 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104111								
7033 W 40TH STREET	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				104112								
7027 40TH STREET	N/A	N	N	1924	1924	Visual Inspection	U	U	L	L		9/27/2024	N				104113								
4424 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104116								
4301 MAPLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104117								
4240 ELMWOOD AVENUE	N/A	N	N	1947	1947	Visual Inspection	U	U	C	U		9/27/2024	N				104118								
3931 EAST AVENUE	N/A	N	N	1975	1975		U	U	U	U		9/27/2024	N				104119								
4027 EUCLID AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				104120								
4227 GROVE AVENUE	N/A	N	N	1937	1937		U	U	U	U		9/27/2024	N				104123								
4319 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				104125								
4208 S GUNDERSON AVENUE	N/A	N	N	2017	2017	Visual Inspection	C	C	C	NL		N/R	N				104126								
4228 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104127								
4145 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104129								
4401 S HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				104130								
3915 GUNDERSON AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				104132								

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
7136 41ST STREET	N/A	N	N	1915	1915		U	U	U	U		9/27/2024	N					104133
4004 CLINTON AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N					104135
4013 GUNDERSON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N					104137
6509 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N					104139
6511 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N					104140
4001 GUNDERSON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					104141
4032 GUNDERSON AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N					104144
7126 W 41ST STREET	N/A	N	N	1915	1915		U	U	U	U		9/27/2024	N					104145
4328 WISCONSIN AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N					104146
4225 S WISCONSIN AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					104147
6408 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					104148
4129 GUNDERSON AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N					104149
3944 ELMWOOD AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N					104150
3932 CLARENCE AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					104152
7039 43RD STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					104153
6416 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					104155
7012 40TH STREET	N/A	N	N	1948	1948		U	U	U	U		9/27/2024	N					104156
4309 MAPLE AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N					104157
4342 WENONAH AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N					104158
3931 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N					104159
4040 CLINTON AVENUE	N/A	N	N	2018	2018	Visual Inspection	C	C	C	NL		N/R	N					104160
4117 MAPLE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N					104161
4441 WISCONSIN AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N					104162
4414 WENONAH AVENUE	N/A	N	N	1956	1956	Visual Inspection	U	U	C	U		12/15/2025	N					104163
4330 GROVE AVENUE	N/A	N	N	1946	1946	Visual Inspection	U	U	L	L		9/27/2024	N					104164
4313 WISCONSIN AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N					104166
4302 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N					104167
7020 43RD STREET	N/A	N	N	1970	1970		U	U	U	U		9/27/2024	N					104168
4123 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N					104169
4305 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N					104170
3932 SCOVILLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N					104171
4115 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					104172
7030 41ST STREET	N/A	N	N	1933	1933		U	U	U	U		9/27/2024	N					104173
3919 OAK PARK AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N					104174
3915 OAK PARK AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N					104175
4420 WISCONSIN AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N					104176
4224 MAPLE AVENUE	N/A	N	N	1980	1980		U	U	U	U		9/27/2024	N					104177
4035 CLARENCE AVENUE	N/A	N	N	2006	2006	Visual Inspection	C	C	C	NL		N/R	N					104178
7017 43RD STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N					104179
3919 HOME AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N					104180

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LX". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4210 S RIDGELAND AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				104181	
4004 ELMWOOD AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				104182	
4232 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104184	
4214 S MAPLE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104185	
3934 OAK PARK AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104186	
4975 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104187	
4122 MAPLE AVENUE	N/A	N	N	2006	2006	Visual Inspection	C	C	C	NL		N/R	N				104188	
4330 CLINTON AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				104190	
3927 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104191	
4112 HOME AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				104193	
4300 WISCONSIN AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				104194	
4230 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104195	
4408 KENILWORTH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104196	
4422 WENONAH AVENUE	LC1T027	N	N	1954	1954	Other - Sample Site	U	L	L	L		9/27/2024	N				104197	
4323 CLINTON AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104198	
4224 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104199	
3945 WESLEY AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				104200	
4141 WISCONSIN AVENUE	N/A	N	N	1973	1973		U	U	U	U		9/27/2024	N				104202	
4009 EUCLID AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				104203	
6704 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104204	
4012 WESLEY AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104206	
3934 EUCLID AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				104207	
4133 HOME AVENUE	N/A	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	N				104209	
4303 MAPLE AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				104210	
6604 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104211	
7024 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				104212	
4315 WENONAH AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				104213	
4410 MAPLE AVENUE	N/A	N	N	1937	1937		U	U	U	U		9/27/2024	N				104217	
4003 CLINTON AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N				104219	
7100 40TH PLACE	N/A	N	N	1986	1986		U	U	U	U		9/27/2024	N				104220	
4036 CLARENCE AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				104221	
3921 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104222	
3913 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				104224	
3925 EUCLID AVENUE	N/A	N	N	1929	1929		U	U	U	U		9/27/2024	N				104226	
3920 CLARENCE AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				104227	
3946 EUCLID AVENUE	N/A	N	N	1922	1922		U	U	U	U		9/27/2024	N				104228	
3938 GROVE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104229	
4044 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104231	
7000 41ST STREET	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104232	
4243 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104233	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4221 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104234	
7130 41ST STREET	N/A	N	N	1913	1913		U	U	U	U		9/27/2024	N				104235	
6626 41ST STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104236	
3911 CLARENCE AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				104238	
3901 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				104239	
4438 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U		9/27/2024	N				104240	
3923 WESLEY AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				104241	
7112 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				104242	
4405 CLINTON AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				104243	
4126 GROVE AVENUE	LC1007	N	N	1987	1987	Other - Sample Site	U	L	L	L		9/27/2024	N				104246	
4124 HOME AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				104247	
4108 GROVE AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				104248	
6645 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104249	
3913 EUCLID AVENUE	N/A	N	N	1937	1937		U	U	U	U		9/27/2024	N				104250	
4202 MAPLE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				104251	
3955 S CLARENCE AVENUE	N/A	N	N	1920	1920		U	U	U	U		9/27/2024	N				104252	
3937 WESLEY AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				104253	
4039 GUNDERSON AVENUE	N/A	N	N	1953	1953	Visual Inspection	U	U	L	L		9/27/2024	N				104256	
4325 KENILWORTH AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				104257	
4138 WISCONSIN AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104258	
4331 KENILWORTH AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				104259	
4234 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104261	
4127 GROVE AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				104262	
6629 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104263	
6627 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104264	
4227 MAPLE AVENUE	N/A	N	N	1935	1935		U	U	U	U		9/27/2024	N				104265	
4445 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104266	
3924 GUNDERSON AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				104267	
7114 43RD STREET	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				104268	
4416 OAK PARK AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104269	
4203 GROVE AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				104270	
7028 40TH STREET	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				104271	
3919 CLARENCE AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				104272	
4325 WISCONSIN AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104273	
3931 SCOVILLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104274	
4109 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104275	
4439 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				104276	
4325 WENONAH AVENUE	N/A	N	N	2004	2004	Visual Inspection	C	C	C	NL		N/R	N				104277	
4211 CLINTON AVENUE	N/A	N	N	2020	2020	Visual Inspection	C	C	C	NL		N/R	N				104278	
4212 WENONAH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104280	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LX". If address is not a lead and copper sample site mark "N/A"	EXAMPLS: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLS: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLS: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLS: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLS: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLS: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLS: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4412 WENONAH AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104283	
4430 OAK PARK AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				104284	
3910 EUCLID AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				104285	
4224 ELMWOOD AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				104286	
6944 W 40TH STREET	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104287	
4029 CLINTON AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				104289	
3911 EUCLID AVENUE	N/A	N	N	1976	1976		U	U	U	U		9/27/2024	N				104290	
3915 GROVE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104291	
3912 EUCLID AVENUE	N/A	N	N	1932	1932		U	U	U	U		9/27/2024	N				104292	
4228 WENONAH AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104293	
4317 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				104294	
4435 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104295	
4400 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104296	
4132 GUNDERSON AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				104297	
4033 HOME AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104298	
4117 WENONAH AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				104299	
4321 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				104300	
4100 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104301	
6413 41ST STREET	N/A	N	N	1956	1956	Visual Inspection	U	U	C	U		9/27/2024	N				104303	
3908 WENONAH AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				104304	
4232 CLINTON AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				104305	
6525 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104306	
4328 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				104307	
4028 RIDGELAND AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104308	
4020 CLINTON AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				104309	
4401 KENILWORTH AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				104310	
4243 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104312	
6900 43RD STREET	N/A	N	N	1932	1932		U	U	U	U		9/27/2024	N				104313	
4433 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U		9/27/2024	N				104314	
6719 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104315	
3916 GROVE AVENUE	N/A	N	N	1944	1944		U	U	U	U		9/27/2024	N				104316	
4019 1/2 EAST AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104317	
3938 GUNDERSON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104318	
4403 WISCONSIN AVENUE	N/A	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	N				104319	
4224 GUNDERSON AVENUE	N/A	N	N	1967	1967		U	U	U	U		9/27/2024	N				104320	
4036 CLINTON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104321	
3927 GUNDERSON AVENUE	N/A	N	N	1923	1923		U	U	U	U		9/27/2024	N				104322	
6515 PERSHING ROAD	N/A	Y	N				U	U	U	U		9/27/2024	N				104323	
4241 ELMWOOD AVENUE	N/A	N	N	1970	1970		U	U	U	U		9/27/2024	N				104326	
4335 KENILWORTH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104328	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4011 SCOVILLE AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				104329	
4401 WISCONSIN AVENUE	N/A	N	N	2022	2022	Visual Inspection	C	C	C	NL		N/R	N				104330	
3933 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104331	
3922 WESLEY AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				104333	
4019 EAST AVENUE	N/A	N	N	2010	2010	Visual Inspection	C	C	C	NL		N/R	N				104334	
6811-A PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104335	
7003 40TH PLACE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104336	
4016 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104337	
4126 WENONAH AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				104338	
6536 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104339	
4219 EAST AVENUE	N/A	N	N	1956	1956	Visual Inspection	C	C	C	NL		N/R	N				104340	
4111 1/2 ELMWOOD AVE	N/A	N	N	1990	1990	Visual Inspection	C	C	C	NL		N/R	N				104341	
7038 43RD STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104342	
4204 WISCONSIN AVENUE	N/A	N	N	1930	1930	Visual Inspection	U	U	L	L		9/27/2024	N				104343	
3923 GROVE AVENUE	N/A	N	N	1938	1938		U	U	U	U		9/27/2024	N				104344	
4105 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104345	
4038 GROVE AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				104347	
7007 43RD STREET	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104348	
6411 41ST STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104349	
3919 WESLEY AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104350	
4000 ELMWOOD AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				104351	
4234 SCOVILLE AVENUE	N/A	N	N	1989	1989		U	U	U	U		9/27/2024	N				104352	
4038 CLINTON AVENUE	N/A	N	N	2000	2000	Visual Inspection	C	C	C	NL		N/R	N				104353	
4122 GUNDERSON AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104354	
4015 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104355	
4235 GUNDERSON AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104356	
4145 ELMWOOD AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				104357	
6712 41ST STREET	N/A	N	N	1919	1919		U	U	U	U		9/27/2024	N				104358	
4401 CLINTON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104359	
3929 GROVE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104360	
7026 41ST STREET	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				104361	
4119 GUNDERSON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104362	
4018 CLARENCE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104363	
4034 EAST AVENUE	N/A	N	N	1949	1949		U	U	U	U		9/27/2024	N				104364	
3931 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104366	
7028 40TH PLACE	N/A	N	N	1976	1976		U	U	U	U		9/27/2024	N				104367	
4300 MAPLE AVENUE	N/A	N	N	1960	1960	Visual Inspection	U	U	C	U		9/27/2024	N				104368	
3921 CLARENCE AVENUE	N/A	N	N	2008	2008	Visual Inspection	C	C	C	NL		N/R	N				104369	
6718 41ST STREET	N/A	N	N	1967	1967		U	U	U	U		9/27/2024	N				104370	
4429 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U		9/27/2024	N				104372	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
7033 PERSHING ROAD	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				104373	
3912 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				104374	
4202 RIDGELAND AVENUE	N/A	N	N	1915	1915	Visual Inspection	U	U	C	U		9/27/2024	N				104375	
4147 GUNDERSON AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				104376	
4019 OAK PARK AVENUE	N/A	N	N	1935	1935		U	U	U	U		9/27/2024	N				104377	
3919 CLINTON AVENUE	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				104378	
4104 OAK PARK AVENUE	N/A	N	N	1911	1911		U	U	U	U		9/27/2024	N				104381	
4123 WENONAH AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				104382	
3912 HOME AVENUE	N/A	N	N	1948	1948		U	U	U	U		9/27/2024	N				104383	
3925 CLARENCE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				104384	
4030 CLINTON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104386	
4212 GROVE AVENUE	LC1T008	N	N	1953	1953	Other - Sample Site	U	L	L	L		9/27/2024	N				104387	
7034 41ST STREET	N/A	N	N	1941	1941		U	U	U	U		9/27/2024	N				104388	
4203 CLINTON AVENUE	N/A	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	N				104389	
43RD & RIDGELAND	N/A	N	N				U	U	U	U		9/27/2024	N				104390	
4012 OAK PARK AVENUE	N/A	N	N	1928	1928		U	U	U	U		9/27/2024	N				104391	
6730 41ST STREET	N/A	N	N	1943	1943		U	U	U	U		9/27/2024	N				104392	
4130 OAK PARK AVENUE	N/A	N	N	1939	1939	Visual Inspection	U	U	C	U		9/27/2024	N				104393	
4001 WESLEY AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104395	
4219 HOME AVENUE	N/A	N	N	1940	1940		U	U	U	U		9/27/2024	N				104396	
4001 HOME AVENUE	N/A	N	N	1942	1942		U	U	U	U		9/27/2024	N				104397	
7040 LORRAINE TERRACE	N/A	N	N	1949	1949	Visual Inspection	U	U	L	L		9/27/2024	N				104398	
6501 41ST STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104399	
7041 40TH STREET	N/A	N	N	1914	1914		U	U	U	U		9/27/2024	N				104400	
4403 HOME AVENUE	N/A	N	N	1927	1927		U	U	U	U		9/27/2024	N				104401	
4140 MAPLE AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				104403	
4215 WISCONSIN AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104404	
4001 CLARENCE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104405	
4221 MAPLE AVENUE	N/A	Y	N	1957	1957		U	U	U	U		9/27/2024	N				104406	
3925 GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104407	
3927 ELMWOOD AVENUE	N/A	N	N	1898	1898		U	U	U	U		9/27/2024	N				104408	
4013 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104409	
4219 WISCONSIN AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104410	
4345 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104411	
4030 ELMWOOD AVENUE	LC1T004	N	N	1924	1924	Other - Sample Site	U	L	L	L		9/27/2024	N				104412	
4207 HARLEM AVENUE	N/A	N	N	1997	1997	Visual Inspection	C	C	C	NL		N/R	N				104413	
4338 CLINTON AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104414	
4451 KENILWORTH AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104415	
3911 GUNDERSON AVENUE	N/A	N	N	1962	1962	Visual Inspection	U	U	C	U		12/15/2025	N				104416	
4139 GUNDERSON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104417	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4408 GROVE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104419	
4231 MAPLE AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104421	
4105 WENONAH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104422	
4324 WISCONSIN AVENUE	N/A	N	N	1959	1959		U	U	U	U		9/27/2024	N				104423	
3917 WISCONSIN AVENUE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				104424	
4221 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104425	
4019 GUNDERSON AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				104426	
3931 EUCLID AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				104427	
3926 CLARENCE AVENUE	N/A	N	N	1914	1914		U	U	U	U		9/27/2024	N				104428	
6725 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104429	
4409 HOME AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104430	
3916 EUCLID AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				104431	
3923 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104432	
4036 WESLEY AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				104433	
6726 41ST STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104434	
4432 KENILWORTH AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				104435	
6829 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104438	
7012 43RD STREET	N/A	N	N	1950	1950		U	U	U	U		9/27/2024	N				104439	
4135 ELMWOOD AVENUE	N/A	N	N	1964	1964		U	U	U	U		9/27/2024	N				104440	
4237 GROVE AVENUE	N/A	N	N	2017	2017	Visual Inspection	C	C	C	NL		N/R	N				104441	
4417 GROVE AVENUE	N/A	N	N	1945	1945		U	U	U	U		9/27/2024	N				104442	
7015 40TH PLACE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				104444	
6409 41ST STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104445	
4131 S HOME AVENUE	N/A	N	N	2020	2020	Visual Inspection	C	C	C	NL		N/R	N				104446	
4218 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104447	
3932 HOME AVENUE	N/A	N	N	1947	1947		U	U	U	U		9/27/2024	N				104448	
3933 WESLEY AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104449	
3938 EUCLID AVENUE	N/A	N	N	1931	1931		U	U	U	U		9/27/2024	N				104450	
4435 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				104451	
6609 41ST STREET	N/A	N	N	1993	1993	Visual Inspection	C	C	C	NL		N/R	N				104452	
4103 S WISCONSIN AVENUE	N/A	N	N	2015	2015	Visual Inspection	C	C	C	NL		N/R	N				104453	
4134 WISCONSIN AVENUE	N/A	N	Y	1953	1953		U	U	C	U		9/27/2024	N				104454	
7116 40TH STREET	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				104455	
4012 GUNDERSON AVENUE	N/A	N	N	1958	1958		U	U	U	U		9/27/2024	N				104456	
4448 CLINTON AVENUE	N/A	N	N	1951	1951		U	U	U	U		9/27/2024	N				104457	
4206 S SCOVILLE AVENUE	N/A	N	N	1916	1916		U	U	U	U		9/27/2024	N				104458	
4401 GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104459	
4301 S KENILWORTH AVENUE	N/A	N	N	1967	1967		U	U	U	U		9/27/2024	N				104460	
3944 OAK PARK AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104461	
4110 EAST AVENUE	N/A	N	N	1992	1992	Visual Inspection	C	C	C	NL		N/R	N				104462	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name			Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026				
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
3916 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104464	
7115 40TH PLACE	N/A	N	N	1917	1917		U	U	U	U		9/27/2024	N				104465	
4117 ELMWOOD AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104466	
7045 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				104467	
4115 WISCONSIN AVENUE	N/A	N	N	1952	1952	Visual Inspection	U	U	C	U		9/27/2024	N				104468	
7037 LORRAINE TERRACE	N/A	N	N	1948	1948	Visual Inspection	U	U	L	L		9/27/2024	N				104469	
4407 KENILWORTH AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				104471	
4015 EAST AVENUE	N/A	N	N	1941	1941		U	U	U	U		9/27/2024	N				104472	
4137 GUNDERSON AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104473	
3926 EAST AVENUE	N/A	N	N	1968	1968		U	U	U	U		9/27/2024	N				104474	
4109 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				104476	
7123 40TH STREET	N/A	N	N	1966	1966		U	U	U	U		9/27/2024	N				104477	
4132 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				104478	
4228 GUNDERSON AVENUE	N/A	N	N	1963	1963		U	U	U	U		9/27/2024	N				104479	
4128 S OAK PARK AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				104480	
3930 GROVE AVENUE	N/A	N	N	2008	2008	Visual Inspection	C	C	C	NL		N/R	N				104481	
4239 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104482	
4035 HOME AVENUE	N/A	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	N				104483	
3800 CICERO AVENUE	N/A	N	N	2022	2022		U	U	U	U		9/27/2024	N				104484	
3904 HOME AVENUE	N/A	N	N	1947	1947	Visual Inspection	U	U	L	L		9/27/2024	N				104485	
4220 WISCONSIN AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104486	
4206 OAK PARK AVENUE	N/A	N	N	1926	1926		U	U	U	U		9/27/2024	N				104487	
4324 MAPLE AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				104488	
4236 SCOVILLE AVENUE	N/A	N	N	2023	2023	Visual Inspection	C	C	C	NL		N/R	N				104489	
4005 HOME AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104491	
4234 SCOVILLE AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				104492	
4132 WISCONSIN AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104493	
4433 HARLEM AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				104494	
6625 PERSHING ROAD	N/A	N	N	1968	1968		U	U	U	U		9/27/2024	N				104495	
4011 SCOVILLE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104496	
3927 GROVE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104497	
6404 41ST STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104498	
4312 MAPLE AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N				104499	
4122 CLINTON AVENUE	N/A	N	N	1952	1952		U	U	U	U		9/27/2024	N				104501	
6817 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104502	
6821 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104503	
4203 GUNDERSON AVENUE	N/A	N	N				U	U	U	U		9/27/2024	N				104504	
4012 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104505	
7035 43RD STREET	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104507	
4203 SCOVILLE AVENUE	N/A	N	N	1961	1961		U	U	U	U		9/27/2024	N				104508	

Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section		Water System Name		Stickney			System ID Number:		IL0313000		Current Inventory Date:		4/15/2026					
*Please enter totals in the empty box next to each category		Total Service lines:		1906	Total Lead:	136	Total Non-Lead:	113	Total Galvanized Requiring replacement:	0	Total Unknown:	1657	Website link to Material Inventory:		https://lead-service-line-inventory-1-novotny.hub.arcgis.com/			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLIS: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLIS: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLIS: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLIS: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLIS: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (I) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLIS: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLIS: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (I) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
4222 GUNDERSON AVENUE	N/A	N	N	1946	1946		U	U	U	U		9/27/2024	N				104509	
4325 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				104510	
4148 GUNDERSON AVENUE	N/A	N	N	1955	1955		U	U	U	U		9/27/2024	N				104511	
4136 GROVE AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104512	
6809-B PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104513	
6807 PERSHING ROAD	N/A	Y	N				U	U	U	U		9/27/2024	N				104514	
6809-C PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104515	
6809-A PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104516	
6805 PERSHING ROAD	N/A	N	N				U	U	U	U		9/27/2024	N				104517	
7018 40TH PLACE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104518	
4016 CLINTON AVENUE	N/A	N	N	1930	1930		U	U	U	U		9/27/2024	N				104519	
4314 MAPLE AVENUE	N/A	N	N	1960	1960		U	U	U	U		9/27/2024	N				104520	
4310 MAPLE AVENUE	N/A	N	N	1962	1962		U	U	U	U		9/27/2024	N				104521	
4127 SCOVILLE AVENUE	N/A	N	N	1922	1922		U	U	U	U		9/27/2024	N				104522	
3941 ELMWOOD AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104523	
4013 EUCLID AVENUE	N/A	N	N	1924	1924		U	U	U	U		9/27/2024	N				104524	
4028 WESLEY AVENUE	N/A	N	N	1957	1957		U	U	U	U		9/27/2024	N				104525	
4406 MAPLE AVENUE	N/A	N	N	1988	1988		U	U	U	U		9/27/2024	N				104526	
6428 41ST STREET	N/A	N	N	1918	1918	Visual Inspection	U	U	C	U		9/27/2024	N				104527	
4138 MAPLE AVENUE	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104528	
4448 KENILWORTH AVENUE	N/A	N	N	1954	1954		U	U	U	U		9/27/2024	N				104529	
6431 41ST STREET	N/A	N	N	1953	1953		U	U	U	U		9/27/2024	N				104530	
4221 S WISCONSIN AVENUE	N/A	N	N	1956	1956		U	U	U	U		9/27/2024	N				104531	
4335 HOME AVENUE	N/A	N	N	1925	1925		U	U	U	U		9/27/2024	N				104533	
4400 HOME AVENUE	N/A	Y	N			Record	U	O	O	O								
4100 SCOVILLE AVENUE	N/A	Y	N			Record	U	O	O	O								